Manhole Inspection Report



Date: 05/07/2018 Weather: Coding: RZMACP

 MH#:
 M-804-080
 Owner:
 NA
 Len. Surveyed:
 4.6

 P.O.#:
 Surveyor:
 Jen Costello
 Rim to Invert:
 5.2

Customer: Cert. #: U-907-5518 Wall Material: Concrete

(reinforced)

Street: Hwy 51 and Jackson St. Project: Hobart, IN
City: Hobart, IN GPS Northing: 2909725.826

Location: GPS Easting: 2909725.826

Drain Area: South GPS Accuracy: Sub-Meter

Cover Shape: Circular Evidence of Surcharge: No
Cover Size: Potential for Runoff: None


Comments:

O&M Index:	2.00	O&M Quick:	2100	O&M Rating:	2.00
Structural Index:	0.00	Structural Quick:	0000	Structural Rating:	0.00
Overall Index:	2.00	Overall Quick:	2100	Overall Rating:	2.00

Wednesday, May 3, 2023

	Position	Code	Observation	Video (sec)	Grade
M-804-0	30				
	<u></u>	MGP	General Photo	10	NA
- 11	1.6	MGO	General Observation	26	NA
- 11	3.9	DSF	Deposits Settled Fine	44	M 2
- 11	4.6	MGO	General Observation	56	NA
Camera Direction					

Code:



Description:	General Photo
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	ACCESS MH

MGP

Wednesday, May 3, 2023



Code: MGO

Description: General Observation

Distance (ft): 1.6
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: UNDERSIDE OF FRAME



Code: **DSF**

Description: Deposits Settled Fine

Distance (ft): 3.9
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 12
Clock To: 12
1st Value:

2nd Value:

Value Percent: 5.000 Step: NO

Remarks:

Code:

Description: General Observation

MGO



Distance (ft): 4.6

Structural Grade: **0**O&M Grade: **0**

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: END SURVEY

Wednesday, May 3, 2023