Manhole Inspection Report



Date: 05/07/2018 Weather: Coding: RZMACP

 MH#:
 M-804-081
 Owner:
 NA
 Len. Surveyed:
 4.6

 P.O.#:
 Surveyor:
 Jen Costello
 Rim to Invert:
 5.5

Customer: Cert. #: U-907-5518 Wall Material: Concrete

(reinforced)

Street: Hwy 51, and Jackson St. Project: Hobart, IN
City: Hobart, IN GPS Northing: 2909738.537

Location: GPS Easting: 2909738.537

Drain Area: South GPS Accuracy: Sub-Meter

Cover Shape: Circular Evidence of Surcharge: No
Cover Size: Potential for Runoff: None


Comments:

2.00 2100 2.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Index: Structural Quick: Structural Rating: 2.00 2100 2.00 Overall Index: Overall Quick: Overall Rating:

Wednesday, May 3, 2023

	Code	Observation	Video (sec)	Grade
M-804-081				
.0	MGP	General Photo	10	NA
1.2	IS	Infil Stain	24	NA
1.2	MGO	General Observation	37	NA
4.6	OBR	Obstacle Rocks	57	M 2
4.6	MGO	General Observation	68	NA
Camera Direction				

Code:



Description:	General Photo
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	ACCESS MH

MGP

Wednesday, May 3, 2023 2



Code: IS

Description: Infil Stain

Distance (ft): 1.2
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 12


Clock To: 12

1st Value:

2nd Value: Value Percent:

Step: NO

Remarks:



Code: MGO

Description: General Observation

Distance (ft): 1.2
Structural Grade: 0
O&M Grade: 0
Clock Start/From:
Clock To:

1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: UNDERSIDE OF FRAME



Code: OBR

Description: Obstacle Rocks


Distance (ft): 4.6
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 12
Clock To: 6
1st Value:

2nd Value: Value Percent: Step:

5.000 NO

Remarks:

Wednesday, May 3, 2023



Code: MGO

Description: General Observation

Distance (ft): 4.6
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: END SURVEY