Manhole Ins	spection Repor	t			ROBOTIC
Date:	05/09/2018	Weather:		Coding:	RZMACP
MH#:	M-805-002	Owner:	NA	Len. Surveyed:	13.7
P.O.#:		Surveyor:	Jen Costello	Rim to Invert:	14.7
Customer:		Cert. #:	U-907-5518	Wall Material:	Concrete (reinforced)
Street:	Hobart Rd. 308' North of 5th St.		Project:	Hobart, IN	
City:	Hobart, IN		GPS Northing:	2909796.926	
Location:			GPS Easting:	2909796.926	
Drain Area:	Southeast		GPS Accuracy:	Sub-Meter	
Cover Shape:	Circular		Evidence of Surcharge:	Νο	
Cover Size: Comments:	22.5		Potential for Runoff:	None	
O&M Index:	0.00	O&M Quick:	0000	O&M Rating:	0.00
Structural Index:	0.00	Structural Qu	ick: 0000	Structural Rating:	0.00
Overall Index:	0.00	Overall Quick	c: 0000	Overall Rating:	0.00

N-E05-02 0 MGP General Photo 10 NA 13.7 MGO General Observation 49 NA
.0 MGP General Photo 10 NA   13.7 MGO General Observation 49 NA
Lection
Le ctio
Le ction



Code:	MGP	
Description:	General Photo	
Distance (ft):	.0	
Distance (ft):	.0	
Structural Grade:	0	
O&M Grade:	0	
Clock Start/From:		
Clock To:		
1st Value:		
2nd Value:		
Value Percent:		
Step:	NO	
Remarks:	ACCESS MH	
Value Percent: Step:		



Code: MGO Description: Gener

MGO General Observation

Distance (ft):	13.7
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	END SURVEY