Manhole Inspection Report



Date: 05/06/2018 Weather: Coding: RZMACP

MH#:M-805-052Owner:NALen. Surveyed:4.3P.O.#:Surveyor:Jen CostelloRim to Invert:5.2Customer:Cert. #:U-907-5518Wall Material:Brick

Street: Linda St. 267' North of 3rd St. Project: Hobart, IN
City: Hobart, IN GPS Northing: 2907047.161

Location: GPS Easting: **2907047.161**

Drain Area: South GPS Accuracy: Sub-Meter

Cover Shape: Circular Evidence of Surcharge: No
Cover Size: Potential for Runoff: None

Comments:

2100 2.00 2.00 O&M Index: O&M Quick: O&M Rating: 6.00 3.00 3200 Structural Quick: Structural Index: Structural Rating: 3221 8.00 Overall Index: 2.67 Overall Quick: Overall Rating:

Wednesday, May 3, 2023

Po	sition Code	Observation	Video (sec)	Grade
VI-805-052				
.0	MGP	General Photo	10	NA
1.0) В	Broken	23	S 3
1.6	6 MGP	General Photo	38	NA
1.6	6 FL	Fracture Longitudinal	48	S 3
3.5	DSF DSF	Deposits Settled Fine	65	M 2
4.3	MGO	General Observation	78	NA
Camera Direction				

Code:



Description:	General Photo	
Distance (ft):	0	
Distance (ft):	.0	
Structural Grade:	0	
O&M Grade:	0	
Clock Start/From:		
Clock To:		
1st Value:		
2nd Value:		
Value Percent:		
Step:	NO	
Remarks:	ACCESS MH	

MGP

Wednesday, May 3, 2023



Code: B
Description: Broken

Distance (ft): 1.0
Structural Grade: 3
O&M Grade: 0
Clock Start/From: 2

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:



Code: MGP

Description: General Photo

Distance (ft): 1.6
Structural Grade: 0

O&M Grade: 0

Clock Start/From:
Clock To:

1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: UNDERSIDE OF FRAME



Code: FL

Description: Fracture Longitudinal

Distance (ft): 1.6
Structural Grade: 3
O&M Grade: 0
Clock Start/From: 9
Clock To:
1st Value:
2nd Value:
Value Percent:

Step: NO

Remarks:

Wednesday, May 3, 2023 3



Code: **DSF**

Description: Deposits Settled Fine

Distance (ft): 3.5
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 12
Clock To: 12

1st Value: 2nd Value:

Value Percent: 5.000 Step: NO

Remarks:



Code: MGO

Description: General Observation

Distance (ft): 4.3
Structural Grade: 0

O&M Grade: 0

Clock Start/From:
Clock To:

1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: END SURVEY