Manhole Ins	spection Repor	rt			RedZo
Date:	04/28/2018	Weather:		Coding:	RZMACP
MH#:	M-806-014	Owner:	NA	Len. Surveyed:	5.8
P.O.#:		Surveyor:	Jen Costello	Rim to Invert:	5.4
Customer:		Cert. #:	U-907-5518	Wall Material:	Brick
Street:	8th St. Memory Ln	. to the Southeast	Project:	Hobart, IN	
City:	Hobart, IN		GPS Northing:	41.5248642	
Location:			GPS Easting:	-87.24835968	
Drain Area:	Southeast		GPS Accuracy:	Nearest Meter	
Cover Shape:	Circular		Evidence of Surcharge:	No	
Cover Size:	22.5		Potential for Runoff:	None	
Comments:					
O&M Index:	2.00	O&M Quick:	2100	O&M Rating:	2.00
Structural Index:	4.00	Structural Qui	ick: 4100	Structural Rating:	4.00
Overall Index:	3.00	Overall Quick	4121	Overall Rating:	6.00

Position	Code	Observation	Video (sec)	Grade
M-806-014				
.0	MGO	General Observation	10	NA
1.5	SAM	Surface Aggregate Missing	24	S 4
1.5	MGO	General Observation	36	NA
4.0	DSGV	Deposits Settled Gravel	54	M 2
5.8	MGO	General Observation	69	NA
Camera Direction				



Code: Description:	MGO General Observation
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	ACCESS MH



Code:SAMDescription:Surface Aggregate Missing

Distance (ft):	1.5
Structural Grade:	4
O&M Grade:	0
Clock Start/From:	12
Clock To:	12
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	



Code: Description:	MGO General Observation
Distance (ft):	1.5
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	UNDERSIDE OF FRAME



Code: Description:	DSGV Deposits Settled Gravel
Distance (ft):	4.0
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	12
Clock To:	12
1st Value:	
2nd Value:	
Value Percent:	5.000
Step:	NO
Remarks:	



Code: Description: MGO General Observation

Distance (ft):	5.8
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	END SURVEY