## **Manhole Inspection Report**



Date:

04/20/2018

Weather:

Coding: **RZMACP** 

MH#:

M-806-020

Owner: NA Len. Surveyed:

10.9 12.2

P.O.#:

Surveyor:

Cert. #:

John Kuglmaier U-1215-07002349 Rim to Invert: Wall Material:

Concrete (reinforced)

Street:

Customer:

Gilberts Ct. 489' South of 6th St.

Project: Hobart, IN

City:

Hobart, IN

2907974.339 **GPS Northing:** 

Location:

GPS Easting:

2907974.339

Drain Area:

Southeast

0000

Cover Shape:

Circular

GPS Accuracy: **Sub-Meter** Evidence of Surcharge: No

Cover Size:

22.5 Potential for Runoff:

Comments:

0.00 O&M Quick: O&M Rating:

0.00 0.00

0.00

O&M Index: Structural Index:

0.00 Structural Quick:

0000 Structural Rating: 0000 Overall Rating:

None

0.00 Overall Index: Overall Quick:

Wednesday, May 3, 2023

1

	Code	Observation	Video (sec)	Grade
л-806-020				
.0	MGP	General Photo	10	NA
1.5	IS	Infil Stain	25	NA
2.1	MGP	General Photo	40	NA
9.0	IS	Infil Stain	67	NA
9.7	MGO	General Observation	80	NA
Camera Direction				



Description:	General Photo	
Distance (ft):	.0	
Structural Grade:	0	
O&M Grade:	0	
Clock Start/From:		
Clock To:		
1st Value:		
2nd Value:		
Value Percent:		
Step:	NO	
Remarks:		

MGP

Wednesday, May 3, 2023

Code:



Code: IS

Description: Infil Stain

Distance (ft): 1.5
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 7
Clock To: 8
1st Value:

2nd Value: Value Percent:

Step: NO

Remarks:



Code: MGP

Description: General Photo

Distance (ft):

Structural Grade:

O&M Grade:

Clock Start/From:

Clock To:

1st Value:

2nd Value: Value Percent:

Step: NO

Remarks:



Description: Infil Stain



Distance (ft): 9.0
Structural Grade: 0

O&M Grade:
Clock Start/From:
8
Clock To:
4

1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:

Wednesday, May 3, 2023



Code: MGO

Description: General Observation

Distance (ft): 9.7
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: Ins. Comp.

Wednesday, May 3, 2023