Manhole Inspection Report					
Date:	04/24/2018	Weather:		Coding:	RZMACP
MH#:	M-806-035	Owner:	NA	Len. Surveyed	: 9.9
P.O.#:		Surveyor:	John Kuglmaier	Rim to Invert:	10.7
Customer:	8.7	Cert. #:	U-1215-07002349	Wall Material:	Concrete (reinforced)
Street:	Intersection of Starboard Ct. and 10t Project: Hobart, IN				
City:	Hobart, IN		GPS Northing:	0.0	
Location:			GPS Easting:	0.0	
Drain Area:	Southeast		GPS Accuracy:	Nearest Meter	
Cover Shape:	Circular		Evidence of Surcharge:	No	
Cover Size: Comments:	22.5		Potential for Runoff:	None	
O&M Index:	2.00	O&M Quick:	2100	O&M Rating:	2.00
Structural Index:	0.00	Structural Qui	ck: 0000	Structural Rating:	0.00
Overall Index:	2.00	Overall Quick:	2100	Overall Rating:	2.00

Position	Code	Observation	Video (sec)	Grade
M-806-035				
.0	MGP	General Photo	10	NA
3.0	MGP	General Photo	30	NA
7.5	DSF	Deposits Settled Fine	53	M 2
8.8	MGO	General Observation	67	NA
Camera Direction				



Code: Description:	MGP General Photo
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	

_



Code: MGP Description: **General Photo** Distance (ft): 3.0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Step: NO Remarks:



Code: Description:	DSF Deposits Settled Fine
Distance (ft): Structural Grade: O&M Grade: Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Step: Remarks:	7.5 0 2 12 12 5.000 NO



Code: Description:	MGO General Observation
Distance (ft):	8.8
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	Ins. Comp.