


# Manhole Inspection Report



|           |                   |           |                        |                |                              |
|-----------|-------------------|-----------|------------------------|----------------|------------------------------|
| Date:     | <b>04/24/2018</b> | Weather:  |                        | Coding:        | <b>RZMACP</b>                |
| MH#:      | <b>M-806-037</b>  | Owner:    | <b>NA</b>              | Len. Surveyed: | <b>6.9</b>                   |
| P.O.#:    |                   | Surveyor: | <b>John Kuglmaier</b>  | Rim to Invert: | <b>7.1</b>                   |
| Customer: | <b>8.7</b>        | Cert. #:  | <b>U-1215-07002349</b> | Wall Material: | <b>Concrete (reinforced)</b> |

|              |                            |                        |                      |
|--------------|----------------------------|------------------------|----------------------|
| Street:      | <b>Port Ct. North end.</b> | Project:               | <b>Hobart, IN</b>    |
| City:        | <b>Hobart, IN</b>          | GPS Northing:          | <b>0.0</b>           |
| Location:    |                            | GPS Easting:           | <b>0.0</b>           |
| Drain Area:  | <b>Southeast</b>           | GPS Accuracy:          | <b>Nearest Meter</b> |
| Cover Shape: | <b>Circular</b>            | Evidence of Surcharge: | <b>No</b>            |
| Cover Size:  | <b>22.5</b>                | Potential for Runoff:  | <b>None</b>          |
| Comments:    |                            |                        |                      |


|                   |             |                   |             |                    |             |
|-------------------|-------------|-------------------|-------------|--------------------|-------------|
| O&M Index:        | <b>0.00</b> | O&M Quick:        | <b>0000</b> | O&M Rating:        | <b>0.00</b> |
| Structural Index: | <b>0.00</b> | Structural Quick: | <b>0000</b> | Structural Rating: | <b>0.00</b> |
| Overall Index:    | <b>0.00</b> | Overall Quick:    | <b>0000</b> | Overall Rating:    | <b>0.00</b> |

|  | Position | Code | Observation         | Video (sec) | Grade |
|--|----------|------|---------------------|-------------|-------|
|  | .0       | MGP  | General Photo       | 10          | NA    |
|  | 2.5      | MGP  | General Photo       | 29          | NA    |
|  | 5.7      | MGO  | General Observation | 49          | NA    |
|  |          |      |                     |             |       |



Code: **MGP**  
Description: **General Photo**

Distance (ft): **.0**  
Structural Grade: **0**  
O&M Grade: **0**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent:  
Step: **NO**  
Remarks:



Code: **MGP**  
Description: **General Photo**  
  
Distance (ft): **2.5**  
Structural Grade: **0**  
O&M Grade: **0**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent:  
Step: **NO**  
Remarks:

---



Code: **MGO**  
Description: **General Observation**  
  
Distance (ft): **5.7**  
Structural Grade: **0**  
O&M Grade: **0**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent:  
Step: **NO**  
Remarks: **Ins. Comp.**