Manhole Inspection Report



Date:

04/20/2018

Weather:

Cert. #:

Coding:

RZMACP

MH#:

M-806-049

Owner: NA Len. Surveyed: 11.3

P.O.#:

Surveyor:

John Kuglmaier

U-1215-07002349

Rim to Invert: Wall Material:

11.5 Concrete

(reinforced)

Street: City:

Customer:

6th St. and Gilbert Court. The South Project:

Hobart, IN 2907989.516

Location:

Hobart, IN

GPS Northing:

Drain Area:

Southeast

GPS Easting: **GPS Accuracy:** 2907989.516 **Sub-Meter**

Cover Shape: Cover Size:

Circular

22.5

Evidence of Surcharge:

No None

Comments:

Potential for Runoff:

O&M Index:	2.00	O&M Quick:	2100	O&M Rating:	2.00	
Structural Index:	0.00	Structural Quick:	0000	Structural Rating:	0.00	
Overall Index:	2.00	Overall Quick:	2100	Overall Rating:	2.00	

1 Wednesday, May 3, 2023

Positio	n Code	Observation	Video (sec)	Grade
M-806-049				
.0	MGP	General Photo	10	NA
2.4	MGP	General Photo	29	NA
8.0	DSF	Deposits Settled Fine	54	M 2
9.7	MGO	General Observation	69	NA
Camera Direction				
Щ				


Code:



Description:	General Photo
Distance (ft): Structural Grade:	.0 0
O&M Grade:	0
Clock Start/From: Clock To:	
1st Value: 2nd Value:	
Value Percent: Step:	NO
Remarks:	

MGP

Wednesday, May 3, 2023 2



Code: MGP

Description: General Photo

Distance (ft): 2.4
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:



Code: **DSF**

Description: Deposits Settled Fine

Distance (ft): 8.0
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 12
Clock To: 12
1st Value:

2nd Value: Value Percent:

Remarks:

10.000

Step: NO



Code: MGO

Description: General Observation

Distance (ft): 9.7
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: Ins. Comp.

Wednesday, May 3, 2023 3