
Manhole Ins	spection Repor	t			RedZor
Date:	04/21/2018	Weather:		Coding:	RZMACP
MH#:	M-807-011	Owner:	NA	Len. Surveyed	: 12.4
P.O.#:		Surveyor:	Jen Costello	Rim to Invert:	13.1
Customer:	8.7	Cert. #:	U-907-5518	Wall Material:	Concrete (reinforced)
Street:	34' South of 10th S	t. 164' East of Ho	Project:	Hobart, IN	
City:	Hobart, IN		GPS Northing:	0.0	
Location:			GPS Easting:	0.0	
Drain Area:	Southeast		GPS Accuracy:	Nearest Meter	
Cover Shape:	Circular		Evidence of Surcharge:	Νο	
Cover Size: Comments:	22.5		Potential for Runoff:	None	
O&M Index:	2.00	O&M Quick:	2200	O&M Rating:	4.00
Structural Index:	0.00	Structural Qu	ick: 0000	Structural Rating:	0.00
Overall Index:	2.00	Overall Quick	c 2200	Overall Rating:	4.00


Position	Code	Observation	Video (sec)	Grade
-807-011				
.0	MGO	General Observation	10	NA
3.0	IW	Infil Weeper	28	M 2
3.0	MGO	General Observation	41	NA
7.3	IW	Infil Weeper	63	M 2
12.4	MSA	Abandoned Survey	85	NA
,				



Code: Description:	MGO General Observation
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	access mh



IW
Infil Weeper
3.0
0
2
5
10
NO



Code: Description:	MGO General Observation
Distance (ft):	3.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	underside of frame



Code: Description:	IW Infil Weeper
Distance (ft):	7.3
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	3
Clock To:	4
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	



Code:	MSA
Description:	Abandoned Survey

Distance (ft):12.4Structural Grade:0O&M Grade:0Clock Start/From:Clock To:1st Value:-2nd Value:-Value Percent:-Step:NORemarks:bench is submerged