## **Manhole Inspection Report**



Date: 04/18/2018 Weather: Coding: RZMACP

 MH#:
 M-807-014
 Owner:
 NA
 Len. Surveyed:
 4.4

 P.O.#:
 Surveyor:
 Jen Costello
 Rim to Invert:
 5.0

Customer: Cert. #: U-907-5518 Wall Material: Concrete

(reinforced)

Street: 14th St. and Illinois St. Project: Hobart, IN
City: Hobart, IN GPS Northing: 2907644.773

Location: GPS Easting: **2907644.773** 

Drain Area: Southeast GPS Accuracy: Sub-Meter

Cover Shape: Circular Evidence of Surcharge: No
Cover Size: Potential for Runoff: None

Comments:

O&M Index:	2.00	O&M Quick:	2100	O&M Rating:	2.00
Structural Index:	0.00	Structural Quick:	0000	Structural Rating:	0.00
Overall Index:	2.00	Overall Quick:	2100	Overall Rating:	2.00

Wednesday, May 3, 2023

	Position	Code	Observation	Video (sec)	Grade
M-807-01	<b>L4</b>				
$\overline{}$	0	MGO	General Observation	10	NA
- 11	1.7	MGO	General Observation	27	NA
- 11	2.5	OBP	Obstacle External Pipe or Cable	42	M 2
- 11	4.4	MGO	General Observation	58	NA
Camera Direction					
Can					



Code: MGO

Description: General Observation

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent:
Step: NO

Remarks: ACCESS MH



Code: MGO

Description: General Observation

Distance (ft): 1.7
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: UNDERSIDE OF FRAME



Code: OBP

Description: Obstacle External Pipe or Cable

Distance (ft): 2.5
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 2
Clock To:

1st Value: 2nd Value:

Value Percent: 5.000 Step: NO

Remarks:

Code: MGO

Description: General Observation



Distance (ft): 4.4
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: END SURVEY

Wednesday, May 3, 2023