## **Manhole Inspection Report**



Date:

Customer:

04/09/2018

Weather:

NA

Coding:

**RZMACP** 

10.6

11.6

MH#:

M-808-005

Owner:

Len. Surveyed:

P.O.#:

Surveyor: Cert. #:

John Kuglmaier U-1215-07002349 Rim to Invert: Wall Material:

Concrete (reinforced)

Street: City:

**Intersection of Capitol Dr. and Union Project:** 

Hobart, IN

**GPS Northing:** 

2908027.752

Location:

GPS Easting:

2908027.752

Drain Area:

GPS Accuracy:

**Sub-Meter** 

Cover Shape:

Southwest Circular

Hobart, IN

Evidence of Surcharge: No

Cover Size:

23.0

Potential for Runoff: None

Comments:

O&M Index:

2.00 0.00 O&M Quick:

2100 0000

O&M Rating: Structural Rating:

2.00 0.00

Structural Index: Overall Index:

Structural Quick: 2.00 Overall Quick:

2100 Overall Rating:

2.00

.0 MGP General Photo 10 NA 2.9 MGP General Photo 30 NA 6.9 IS Infil Stain 51 NA 7.9 DAZ Deposits Attached Other 65 M 2 8.8 MGO General Observation 78 NA	Position	Code	Observation	Video (sec)	Grade
.0         MGP         General Photo         10         NA           2.9         MGP         General Photo         30         NA           6.9         IS         Infil Stain         51         NA           7.9         DAZ         Deposits Attached Other         65         M 2           8.8         MGO         General Observation         78         NA	-808-005				
6.9 IS Infil Stain 51 NA 7.9 DAZ Deposits Attached Other 65 M 2 8.8 MGO General Observation 78 NA		MGP	General Photo	10	NA
7.9 DAZ Deposits Attached Other 65 M 2  8.8 MGO General Observation 78 NA	2.9	MGP	General Photo	30	NA
8.8 MGO General Observation 78 NA	6.9	IS	Infil Stain	51	NA
	7.9	DAZ	Deposits Attached Other	65	M 2
	8.8	MGO	General Observation	78	NA

Code:



Description:	<b>General Photo</b>
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	

MGP

Wednesday, May 3, 2023



Code: MGP

Description: General Photo

Distance (ft): 2.9
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Step: NO

Remarks:



Code: IS

Description: Infil Stain

Distance (ft): 6.9
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 6

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:

Code: DAZ

Description: Deposits Attached Other



Distance (ft): 7.9

Structural Grade: 0

O&M Grade: 2

Clock Start/From: 12

Clock To: 12

1st Value: 2nd Value:

Value Percent: 5.000 Step: NO

Remarks: Mixed materials

Wednesday, May 3, 2023



Code: MGO

Description: General Observation

Distance (ft): 8.8
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: Ins. Comp.

Wednesday, May 3, 2023 4