Manhole Inspection Report



Date: 04/09/2018 Weather: Coding: RZMACP

 MH#:
 M-808-012
 Owner:
 NA
 Len. Surveyed:
 9.7

 P.O.#:
 Surveyor:
 John Kuglmaier
 Rim to Invert:
 10.4

U-1215-07002349

(reinforced)

Concrete

Wall Material:

Street: Independence Dr. 116' East of Capit Project: Hobart, IN

City: Hobart, IN GPS Northing: 0.0

Location: GPS Easting: **0.0**

Drain Area: Southwest GPS Accuracy: Nearest Meter

Cert. #:

Cover Shape: Circular Evidence of Surcharge: No
Cover Size: 23.0 Potential for Runoff: None

Comments:

Customer:

O&M Index:	1.00	O&M Quick:	1100	O&M Rating:	1.00
Structural Index:	0.00	Structural Quick:	0000	Structural Rating:	0.00
Overall Index:	1.00	Overall Quick:	1100	Overall Rating:	1.00

Wednesday, May 3, 2023

	Position	Code	Observation	Video (sec)	Grade
1-808-012	2				
	.0	MGP	General Photo	10	NA
	.0	RFJ	Roots Fine Joint	21	M 1
ш	2.5	MGP	General Photo	40	NA
	7.9	MGO	General Observation	64	NA
ш					
ш					
.					
Camera Direction					
e					
Ę					
- 111					
- 111					
- 11					
- 11					
- 11					
- 11					



Description:	General Photo		
Distance (ft):	.0		
Structural Grade:	0		
O&M Grade:	0		
Clock Start/From:			
Clock To:			
1st Value:			
2nd Value:			
Value Percent:			
Step:	NO		
Remarks:			

MGP

Wednesday, May 3, 2023 2

Code:



Code: RFJ

Description: Roots Fine Joint

Distance (ft): .0
Structural Grade: 0
O&M Grade: 1
Clock Start/From: 1
Clock To: 11

1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:



Code: MGP

Description: General Photo

Distance (ft): 2.5
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:



Code: MGO

Description: General Observation

Distance (ft): 7.9
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: Ins. Comp.

Wednesday, May 3, 2023 3