Manhole Inspection Report

Southwest



Date: 04/09/2018 Coding: Weather: **RZMACP**

M-808-014 MH#: Owner: NA Len. Surveyed: 8.6 P.O.#: John Kuglmaier 9.0 Surveyor: Rim to Invert:

U-1215-07002349 Customer: Cert. #: Wall Material: **Concrete**

(reinforced)

Independence Dr. and Liberty St. Street: Project: Hobart, IN Hobart, IN City: **GPS Northing:** 2909392.112

Location: GPS Easting: 2909392.112

GPS Accuracy: Cover Shape: Circular Evidence of Surcharge: No Cover Size: 23.0 Potential for Runoff: None

Comments:

Drain Area:

2.00 2100 2.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Index: Structural Quick: Structural Rating: 2.00 2100 2.00 Overall Index: Overall Quick: Overall Rating:

Sub-Meter


Wednesday, May 3, 2023 1

	Position	Code	Observation	Video (sec)	Grade
N-808-014					
	0	MGP	General Photo	10	NA
2	2.4	MGP	General Photo	29	NA
[5	5.4	DAZ	Deposits Attached Other	48	M 2
	7.4	MGO	General Observation	64	NA
- 11					
-111					
<u> </u>					
Ĭ					
Camera Direction					
E					
•					
- 111					
- 111					
- 111					
- 11					
- 11					
- 11					
	-				



Code:	MGP
Description:	General Photo
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	

2 Wednesday, May 3, 2023



Code: MGP

Description: General Photo

Distance (ft): 2.4
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value:

2nd Value: Value Percent:

Step: NO

Remarks:



Code: DAZ

Description: Deposits Attached Other

Distance (ft): 5.4
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 12
Clock To: 12
1st Value:

2nd Value: Value Percent:

Value Percent: 5.000 Step: NO

Remarks: Mixed materials



Code: MGO

Description: General Observation

Distance (ft): 7.4
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:

Step: NO

Remarks: Ins. Comp.

Wednesday, May 3, 2023