## **Manhole Inspection Report**



Date: 04/13/2018 Weather: Coding: RZMACP

MH#: M-809-003 Owner: NA Len. Surveyed: 6.2
P.O.#: Surveyor: John Kuglmaier Rim to Invert: 6.7

Customer: Cert. #: U-1215-07002349 Wall Material: Concrete

(reinforced)

Street: Grosbeak Ct. 293' South of Tanager Project: Hobart, IN

 City:
 Hobart, IN
 GPS Northing:
 2908882.722

 Location:
 GPS Easting:
 2908882.722

Drain Area: Southwest GPS Accuracy: Sub-Meter

Cover Shape: Circular Evidence of Surcharge: No
Cover Size: Potential for Runoff: None

Comments:

O&M Index:	0.00	O&M Quick:	0000	O&M Rating:	0.00
Structural Index:	0.00	Structural Quick:	0000	Structural Rating:	0.00
Overall Index:	0.00	Overall Quick:	0000	Overall Rating:	0.00

Wednesday, May 3, 2023

Ро	sition Code	Observation	Video (sec	) Grade
M-809-003				
.0	MGP	General Photo	10	NA
2.4	MGP	General Photo	29	NA
4.8	MG0	General Observation	47	NA
				_
<u> </u>				
rect				
Camera Direction				
a a				
°				
1111				
*				
111				
- 11				
- 11				
- 11				
- 11				

Code:



Description:	<b>General Photo</b>	
Distance (ft):	0	
Distance (ft):	.0	
Structural Grade:	0	
O&M Grade:	0	
Clock Start/From:		
Clock To:		
1st Value:		
2nd Value:		
Value Percent:		
Step:	NO	
Remarks:		

MGP

Wednesday, May 3, 2023



Code: MGP

Description: General Photo

Distance (ft): 2.4
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:



Code: MGO

Description: General Observation

Distance (ft): 4.8
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value:

2nd Value: Value Percent:

Step: NO

Remarks: Ins. Comp.