Manhole Inspection Report



Date:

04/13/2018

Weather:

Coding:

RZMACP

4.8

MH#:

M-809-008

Owner: NA Len. Surveyed:

P.O.#:

John Kuglmaier Surveyor:

Rim to Invert:

Customer:

U-1215-07002349 Cert. #:

Wall Material:

Concrete (reinforced)

Street: City:

Tanager St. 433' East of Grosbeak Ct. Project:

Hobart, IN 2909333.052

Location:

Hobart, IN

GPS Northing: GPS Easting:

2909333.052

Drain Area:

Southwest

GPS Accuracy: **Sub-Meter**

Cover Shape:

Circular

Evidence of Surcharge:

No

Cover Size:

22.5

Potential for Runoff: None

Comments:

O&M Index: Structural Index:

Overall Index:

0.00

0.00 O&M Quick: 0.00 Structural Quick:

Overall Quick:

0000 O&M Rating: 0000 Structural Rating: 0000 Overall Rating:

0.00 0.00

0.00

Wednesday, May 3, 2023

| Position | Code | Observation | Video (sec) | Grade |
|------------------|------|---------------------|-------------|-------|
| И-809-008 | | | | |
| .0 | MGP | General Photo | 10 | NA |
| .4 | IS | Infil Stain | 23 | NA |
| 2.6 | MGP | General Photo | 41 | NA |
| 3.9 | MGO | General Observation | 57 | NA |
| Camera Direction | | | | |



Description: **General Photo** Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: NO Step: Remarks:

MGP

Wednesday, May 3, 2023 2

Code:



Code: IS

Description: Infil Stain

Distance (ft): .4

Structural Grade: 0

O&M Grade: 0

Clock Start/From: 5


Clock To: 1

1st Value:

2nd Value: Value Percent:

Step: NO

Remarks:



Code: MGP

Description: General Photo

Distance (ft): 2.6
Structural Grade: 0
O&M Grade: 0
Clock Start/From:
Clock To:
1st Value:

2nd Value: Value Percent:

Step: NO

Remarks:

Code:

MGO

Description: General Observation



Distance (ft): 3.9

Structural Grade: **0**O&M Grade: **0**

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Step: NO

Remarks: Ins. Comp.

Wednesday, May 3, 2023 3