Manhole Inspection Report



Date: 04/13/2018 Weather: Coding: RZMACP

MH#: M-809-012 Owner: NA Len. Surveyed: 9.1
P.O.#: Surveyor: John Kuglmaier Rim to Invert: 9.9

Customer: Cert. #: U-1215-07002349 Wall Material: Concrete

(reinforced)

Street: Grosbeak Ct. 179' South of Tanager Project: Hobart, IN

City: Hobart, IN GPS Northing: 2909028.16
Location: GPS Easting: 2909028.16

Drain Area: Southwest GPS Accuracy: Sub-Meter

Cover Shape: Circular Evidence of Surcharge: No
Cover Size: Potential for Runoff: None

Comments:

2.00 2100 2.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Index: Structural Quick: Structural Rating: 2.00 2100 2.00 Overall Index: Overall Quick: Overall Rating:

Wednesday, May 3, 2023

	Position	Code	Observation	Video (sec)	Grade
M-809-0	12				
	0. 🗸	MGP	General Photo	10	NA
- 11	2.8	MGP	General Photo	29	NA
- 11	6.1	DAZ	Deposits Attached Other	50	M 2
- 11	8.1	MGO	General Observation	65	NA
Camera Direction					


Code:



Description:	General Photo
Distance (ft): Structural Grade:	.0 0
O&M Grade:	0
Clock Start/From: Clock To:	
1st Value: 2nd Value:	
Value Percent: Step:	NO
Remarks:	

MGP

Wednesday, May 3, 2023



Code: MGP

Description: General Photo

Distance (ft): 2.8
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:



Code: DAZ

Description: Deposits Attached Other

Distance (ft): 6.1
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 12
Clock To: 12
1st Value:

2nd Value:

Value Percent: 5.000 Step: NO

Remarks: Mixed materials



Code: MGO

Description: General Observation

Distance (ft): 8.1
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: Ins. Comp.

Wednesday, May 3, 2023 3