Manhole Inspection Report



Date:

04/13/2018

Weather:

Coding:

RZMACP

7.0

MH#:

M-809-014

Owner:

Len. Surveyed:

P.O.#:

John Kuglmaier Surveyor:

Rim to Invert:

Customer:

U-1215-07002349 Cert. #:

NA

Wall Material:

Concrete (reinforced)

Street: City:

Tanager St. 278' Southeast of Grosb Project:

GPS Northing:

Hobart, IN 2909336.613

Location:

Drain Area:

GPS Easting:

2909336.613

Cover Shape:

Southwest

Hobart, IN

GPS Accuracy:

Sub-Meter

Cover Size:

Circular

22.5

Evidence of Surcharge: No Potential for Runoff: None

Comments:

2.00

O&M Quick:

2100 0000

2100

O&M Rating: Structural Rating:

Overall Rating:

2.00 0.00 2.00

O&M Index: Structural Index: Overall Index:

0.00 Structural Quick: 2.00

Overall Quick:

Wednesday, May 3, 2023

ſ	Position	Code	Observation	Video (sec)	Grade
1-809-014					
	0	MGP	General Photo	10	NA
2	6	MGP	General Photo	29	NA
[3	3.9	DSF	Deposits Settled Fine	45	M 2
ΙŒ	5.0	MGO	General Observation	61	NA
<u> </u>					
Camera Direction					
ш					
ш					
ш					
ш					
ш					
Ш	_				



Description: **General Photo** Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Step: NO Remarks:

MGP

Wednesday, May 3, 2023 2

Code:



Code: MGP

Description: General Photo

Distance (ft): 2.6
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:



Code: **DSF**

Description: Deposits Settled Fine

Distance (ft): 3.9
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 1
Clock To: 6
1st Value:

Value Percent: 5.000 Step: NO

Remarks:

2nd Value:

Code: MGO

Description: General Observation



Distance (ft): **6.0**Structural Grade: **0**

O&M Grade: **0**

Clock Start/From: Clock To:

1st Value: 2nd Value:

Value Percent:

Step: NO

Remarks: Ins. Comp.