Date:	04/12/2018	Weather:		Coding:	RZMACP
MH#:	M-809-023	Owner:	NA	Len. Surveyed:	6.1
P.O.#:		Surveyor:	John Kuglmaier	Rim to Invert:	6.6
Customer:		Cert. #:	U-1215-07002349	Wall Material:	Concrete (reinforced)
Street:	Bracken Parkway.	Hobart Rd. to the	Project:	Hobart, IN	
City:	Hobart, IN	(GPS Northing:	2909909.605	
Location:		(GPS Easting:	2909909.605	
Drain Area:	Southwest	(GPS Accuracy:	Sub-Meter	
Cover Shape:	Circular	E	Evidence of Surcharge:	No	
Cover Size: Comments:	22.5	I	Potential for Runoff:	None	
O&M Index:	1.00	O&M Quick:	1100	O&M Rating:	1.00
Structural Index:	0.00	Structural Quid	ck: 0000	Structural Rating:	0.00
Overall Index:	1.00	Overall Quick:	1100	Overall Rating:	1.00

Position	Code	Observation	Video (sec)	Grade
1-809-023				
.0	MGP	General Photo	10	NA
.9	RFJ	Roots Fine Joint	24	M 1
2.3	MGP	General Photo	41	NA
/ 5.0	MGO	General Observation	60	NA
Camera Direction				




Code:	MGP
Description:	General Photo
	_
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	



Code:	RFJ
Description:	Roots Fine Joint

Distance (ft):	.9
Structural Grade:	0
O&M Grade:	1
Clock Start/From:	1
Clock To:	2
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	



Code: Description:	MGP General Photo
Distance (ft):	2.3
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	



Code: Description:	MGO General Observation
Distance (ft):	5.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	Ins. Comp.