Manhole Inspection Report



04/11/2018 Date:

M-809-028

Weather: Owner:

Coding:

RZMACP

5.7

6.2

MH#: P.O.#:

NA

John Kuglmaier

Len. Surveyed: Rim to Invert:

Customer:

Surveyor: U-1215-07002349 Cert. #:

Wall Material:

Concrete (reinforced)

Street: City:

Murrelet St. 648' West of Liberty St. Project:

GPS Northing:

Hobart, IN 2908997.965

Location:

Drain Area:

GPS Easting:

2908997.965

Cover Shape:

Southwest Circular

Hobart, IN

GPS Accuracy: **Sub-Meter** Evidence of Surcharge:

No

Cover Size:

22.5

Potential for Runoff: None

Comments:

O&M Index:

0.00 0.00

O&M Quick: Structural Quick:

0000 0000 0000

O&M Rating: Structural Rating: Overall Rating:

0.00 0.00 0.00

Structural Index: Overall Index:

0.00 Overall Quick:

Wednesday, May 3, 2023

1

Position	Code	Observation	Video (sec)	Grade
Л- 809-028				
.0	MGP	General Photo	10	NA
2.0	MGP	General Photo	28	NA
4.7	MGO	General Observation	47	NA
Camera Direction				



Description:	General Photo	
Distance (ft): Structural Grade: O&M Grade: Clock Start/From: Clock To:	.0 0 0	
1st Value: 2nd Value: Value Percent:		
Step: Remarks:	NO	

MGP

Wednesday, May 3, 2023 2

Code:



Code: MGP

Description: General Photo

Distance (ft): 2.0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:



Code: MGO

Description: General Observation

Distance (ft): 4.7
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: Ins. Comp.

3