
Date:	04/11/2018	Weather:		Coding:	RZMACP
MH#:	M-809-029	Owner:	NA	Len. Surveyed:	6.6
P.O.#:		Surveyor:	John Kuglmaier	Rim to Invert:	6.5
Customer:		Cert. #:	U-1215-07002349	Wall Material:	Concrete (reinforced)
Street:	Murrelet St. 112' Ea	ast of Eider Ave.	Project:	Hobart, IN	
City:	Hobart, IN		GPS Northing:	2908760.687	
Location:			GPS Easting:	2908760.687	
Drain Area:	Southwest		GPS Accuracy:	Sub-Meter	
Cover Shape:	Circular		Evidence of Surcharge:	No	
Cover Size: Comments:	22.5		Potential for Runoff:	None	
O&M Index:	0.00	O&M Quick:	0000	O&M Rating:	0.00
Structural Index:	0.00	Structural Qu	ick: 0000	Structural Rating:	0.00
Overall Index:	0.00	Overall Quick	c: 0000	Overall Rating:	0.00

Position	Code	Observation	Video (sec)	Grade
-809-029				
.0	MGP	General Photo	10	NA
1.7	IS	Infil Stain	25	NA
2.5	MGP	General Photo	41	NA
5.3	MGO	General Observation	60	NA



Code:	MGP
Description:	General Photo
	_
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	



Code:	IS
Description:	Infil Stain
	4 7
Distance (ft):	1.7
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	2
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	



Code: Description:	MGP General Photo
Distance (ft):	2.5
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	
•	



Code: Description:	MGO General Observation
Distance (ft):	5.3
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	Ins. Comp.