## **Manhole Inspection Report**



04/12/2018 Date:

M-809-046

Weather:

Coding:

**RZMACP** 

5.1

MH#:

Owner:

Len. Surveyed: 4.5

P.O.#:

Surveyor: Cert. #:

Rim to Invert: John Kuglmaier U-1215-07002349 Wall Material:

Concrete (reinforced)

Street: City:

Customer:

Kestrel St. 146' West of Tanager St.

Project: **GPS Northing:** 

NA

Hobart, IN 2908494.219

Location:

Hobart, IN

2908494.219

Drain Area:

Southwest

22.5

GPS Easting:

**Sub-Meter** 

Cover Shape: Cover Size:

Circular

GPS Accuracy: Evidence of Surcharge:

No Potential for Runoff: None

0000

0000

0000

Comments:

O&M Index:

0.00 O&M Quick: 0.00

Structural Quick:

O&M Rating: Structural Rating:

Overall Rating:

0.00 0.00 0.00

Structural Index: Overall Index:

0.00 Overall Quick:

Wednesday, May 3, 2023

1

Position	Code	Observation	Video (sec)	Grade
1-809-046				
.0	MGP	General Photo	10	NA
2.4	MGP	General Photo	29	NA
3.6	MGO	General Observation	45	NA
Camera Direction				


Code:



Description: **General Photo** Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Step: NO Remarks:

MGP

Wednesday, May 3, 2023 2



Code: MGP

Description: General Photo

Distance (ft): 2.4
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:



Code: MGO

Description: General Observation

Distance (ft): 3.6
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To:

1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: Ins. Comp.