Manhole Inspection Report



Date: 04/12/2018 Weather: Coding: RZMACP

 MH#:
 M-809-060
 Owner:
 NA
 Len. Surveyed:
 7.3

 P.O.#:
 Surveyor:
 John Kuglmaier
 Rim to Invert:
 7.5

Customer: Cert. #: U-1215-07002349 Wall Material: Concrete

(reinforced)

Street: South of Bracken Parkway. 481' Wes Project: Hobart, IN

City: Hobart, IN GPS Northing: 0.0

Location: GPS Easting: **0.0**

Drain Area: Southwest GPS Accuracy: Nearest Meter

Cover Shape: Circular Evidence of Surcharge: Yes

Cover Size: Potential for Runoff: None

Comments:

O&M Index:	2.00	O&M Quick:	2100	O&M Rating:	2.00
Structural Index:	0.00	Structural Quick:	0000	Structural Rating:	0.00
Overall Index:	2.00	Overall Quick:	2100	Overall Rating:	2.00

Wednesday, May 3, 2023

	Position	Code	Observation	Video (sec)	Grade
M-809-06	60				
	0	MGP	General Photo	10	NA
- 11	2.1	MGP	General Photo	28	NA
- 11	4.9	DSF	Deposits Settled Fine	47	M 2
- 11	5.7	MGO	General Observation	61	NA
Camera Direction					

Code:



Description:	General Photo	
Distance (ft):	.0	
Structural Grade:	0	
O&M Grade:	0	
Clock Start/From:		
Clock To:		
1st Value:		
2nd Value:		
Value Percent:		
Step:	NO	
Remarks:		

MGP

Wednesday, May 3, 2023



Code: MGP

Description: General Photo

Distance (ft): 2.1
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:



Code: **DSF**

Description: Deposits Settled Fine

Distance (ft): 4.9
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 12
Clock To: 12

1st Value: 2nd Value:

Value Percent: 5.000 Step: NO

Remarks:

Code:

MGO

Description: General Observation



Distance (ft): 5.7

Structural Grade: **0**O&M Grade: **0**

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: Ins. Comp.

Wednesday, May 3, 2023