Manhole Inspection Report



Date: 03/24/2018 Weather: Coding: RZMACP

 MH#:
 M-902-037
 Owner:
 NA
 Len. Surveyed:
 6.9

 P.O.#:
 Surveyor:
 John Kuglmaier
 Rim to Invert:
 7.4

Customer: Cert. #: U-1215-07002349 Wall Material: Concrete

(reinforced)

Street: Randolph St. 185' South of 34th Ave. Project: Hobart, IN

City: Hobart, IN GPS Northing: 0.0

Location: GPS Easting: **0.0**Drain Area: Northeast GPS Accuracy: Nearest Meter

Cover Shape: Circular Evidence of Surcharge: Yes
Cover Size: 23.0 Potential for Runoff: None


Comments:

O&M Index:	0.00	O&M Quick:	0000	O&M Rating:	0.00
Structural Index:	0.00	Structural Quick:	0000	Structural Rating:	0.00
Overall Index:	0.00	Overall Ouick:	0000	Overall Rating:	0.00

Wednesday, May 3, 2023

	Position	Code	Observation	Video (sec)	Grade
M-902-03	37				
	0	MGP	General Photo	10	NA
- 11	2.1	MGP	General Photo	28	NA
- 11	4.1	MGO	General Observation	45	NA
- 11	5.5	MGO	General Observation	60	NA
Camera Direction					

Code:



Description:	General Photo
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	

MGP

Wednesday, May 3, 2023



Code: MGP

Description: General Photo


Distance (ft): 2.1
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Step: NO

Remarks:



Code: MGO

Description: General Observation

Distance (ft): 4.1
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: Surcharge



Code: MGO

Description: General Observation

Distance (ft): 5.5
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock StartyFfor Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: Ins. Comp.

Wednesday, May 3, 2023