## **Manhole Inspection Report**



Date: 03/23/2018 Weather: Coding: RZMACP

 MH#:
 M-902-052
 Owner:
 NA
 Len. Surveyed:
 4.8

 P.O.#:
 Surveyor:
 John Kuglmaier
 Rim to Invert:
 6.0

Customer: Cert. #: U-1215-07002349 Wall Material: Concrete

(reinforced)

Street: **36th Ave. 101' West of St Joseph's PI** Project: **Hobart, IN** 

City: Hobart, IN GPS Northing: 0.0

Location: GPS Easting: **0.0** 

Drain Area: Northeast GPS Accuracy: Nearest Meter

Cover Shape: Circular Evidence of Surcharge: No
Cover Size: 23.0 Potential for Runoff: None


Comments:

O&M Index:	2.00	O&M Quick:	2100	O&M Rating:	2.00
Structural Index:	0.00	Structural Quick:	0000	Structural Rating:	0.00
Overall Index:	2.00	Overall Quick:	2100	Overall Rating:	2.00

Wednesday, May 3, 2023

Position	Code	Observation	Video (sec)	Grade
M-902-052				
.0	MGP	General Photo	10	NA
2.1	MGP	General Photo	28	NA
2.9	DAZ	Deposits Attached Other	43	M 2
4.0	MGO	General Observation	57	NA
Camera Direction				

Code:



Description:	General Photo		
Distance (ft):	.0		
Structural Grade:	0		
O&M Grade:	0		
Clock Start/From:			
Clock To:			
1st Value:			
2nd Value:			
Value Percent:			
Step:	NO		
Remarks:			

MGP

Wednesday, May 3, 2023



Code: MGP

Description: General Photo

Distance (ft): 2.1
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:



Code: DAZ

Description: Deposits Attached Other

Distance (ft): 2.9
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 12
Clock To: 12
1st Value:

2nd Value:
Value Percent: 10.000
Step: NO

Remarks: Mixed materials



Code: MGO

Description: General Observation

Distance (ft): 4.0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock StartyFrom Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: Ins. Comp.

Wednesday, May 3, 2023 3