Manhole Inspection Report



Date: 03/23/2018 Weather: Coding: RZMACP

 MH#:
 M-902-060
 Owner:
 NA
 Len. Surveyed:
 6.5

 P.O.#:
 Surveyor:
 John Kuglmaier
 Rim to Invert:
 7.4

Customer: Cert. #: U-1215-07002349 Wall Material: Concrete

(reinforced)

Street: Rush Pl. 242' South of 36th Ave. Project: Hobart, IN

City: Hobart, IN GPS Northing: 0.0 Location: GPS Easting: 0.0

Drain Area: Northeast GPS Accuracy: Nearest Meter

Cover Shape: Circular Evidence of Surcharge: No
Cover Size: 23.0 Potential for Runoff: None

Comments:

O&M Index:	2.00	O&M Quick:	2100	O&M Rating:	2.00
Structural Index:	0.00	Structural Quick:	0000	Structural Rating:	0.00
Overall Index:	2.00	Overall Quick:	2100	Overall Rating:	2.00

Wednesday, May 3, 2023

	Position	Code	Observation	Video (sec)	Grade
M-902-96	0				
\mathcal{A}	.0	MGP	General Photo	10	NA
- 11	2.2	MGP	General Photo	28	NA
- 11	4.1	DSF	Deposits Settled Fine	46	M 2
- 11	5.7	MGO	General Observation	60	NA
Camera Direction					


Code:



Description: **General Photo** Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: NO Step: Remarks:

MGP

Wednesday, May 3, 2023 2



Code: MGP

Description: General Photo

Distance (ft): 2.2
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:



Code: **DSF**

Description: Deposits Settled Fine

Distance (ft): 4.1
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 12
Clock To: 12
1st Value:

Value Percent: 5.000 Step: NO

Remarks:

2nd Value:

Code: MGO

Description: General Observation



Distance (ft): 5.7
Structural Grade: 0

O&M Grade: **0**

Clock Start/From: Clock To:

1st Value: 2nd Value:

Value Percent:

Step: NO

Remarks: Ins. Comp.

Wednesday, May 3, 2023 3