
Date:	03/20/2018	Weather:		Coding:	RZMACP
MH#:	M-903-010	Owner:	NA	Len. Surveyed:	3.6
P.O.#:		Surveyor:	John Kuglmaier	Rim to Invert:	5.0
Customer:		Cert. #:	U-1215-07002349	Wall Material:	Concrete (reinforced)
Street:	South of Hwy 6 and	d West of Union S	Project:	Hobart, IN	
City:	Hobart, IN	(GPS Northing:	2912127.171	
Location:			GPS Easting:	2912127.171	
Drain Area:	Northeast	(GPS Accuracy:	Sub-Meter	
Cover Shape:	Circular	E	Evidence of Surcharge:	Yes	
Cover Size: Comments:	23.0	F	Potential for Runoff:	None	
O&M Index:	0.00	O&M Quick:	0000	O&M Rating:	0.00
Structural Index:	0.00	Structural Quic	ck: 0000	Structural Rating:	0.00
Overall Index:	0.00	Overall Quick:	0000	Overall Rating:	0.00

Position	Code	Observation	Video (sec)	Grade
л-903-010				
0. /	MGP	General Photo	10	NA
1.5	MGO	General Observation	25	NA
1.9	MGP	General Photo	39	NA
3.0	MGO	General Observation	55	NA
Camera Direction				



Code: Description:	MGP General Photo
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	




Code: MGO Description: Gener

General Observation

Distance (ft):	1.5
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	Surcharge



Code: Description:	MGP General Photo
Distance (ft):	1.9
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	



Code: Description:	MGO General Observation
Distance (ft):	3.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	Ins. Comp.