Date:	03/21/2018	Weather:		Coding:	RZMACP
MH#:	M-903-039	Owner:	NA	Len. Surveyed:	5.8
P.O.#:		Surveyor:	John Kuglmaier	Rim to Invert:	7.3
Customer:		Cert. #:	U-1215-07002349	Wall Material:	Concrete (reinforced)
Street:	687' East of Hwy 51. and North of 38 Project: Hobart, IN				
City:	Hobart, IN	(GPS Northing:	0.0	
Location:		(GPS Easting:	0.0	
Drain Area:	Northeast	(GPS Accuracy:	Nearest Meter No	
Cover Shape:	Circular	E	Evidence of Surcharge:		
Cover Size: Comments:	23.0		Potential for Runoff:	None	
O&M Index:	2.00	O&M Quick:	2100	O&M Rating:	2.00
Structural Index:	0.00	Structural Quic	ck: 0000	Structural Rating:	0.00
Overall Index:	2.00	Overall Quick:	2100	Overall Rating:	2.00

F	osition	Code	Observation	Video (sec)	Grade
1-903-039					
)	MGP	General Photo	10	NA
2	.4	MGP	General Photo	29	NA
3	.9	DSF	Deposits Settled Fine	45	M 2
5	.1	MGO	General Observation	59	NA
, T					



Code: Description:	MGP General Photo
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	



MGP
General Photo
2.4
0
0
NO



Code: Description:	DSF Deposits Settled Fine
Distance (ft): Structural Grade: O&M Grade: Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Step: Remarks:	3.9 0 2 12 12 5.000 NO



Code: Description:	MGO General Observation
Distance (ft):	5.1
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	Ins. Comp.