Manhole Inspection Report



Date: 03/28/2018 Weather: Coding:

 MH#:
 M-903-047
 Owner:
 NA
 Len. Surveyed:
 4.0

 P.O.#:
 Surveyor:
 John Kuglmaier
 Rim to Invert:
 6.1

Customer: Cert. #: U-1215-07002349 Wall Material: Concrete

(reinforced)

RZMACP

Street: West of Brandt St. 474' South of Ran Project: Hobart, IN

City: Hobart, IN GPS Northing: 0.0

Location: GPS Easting: **0.0**

Drain Area: Northeast GPS Accuracy: Nearest Meter

Cover Shape: Circular Evidence of Surcharge: No
Cover Size: 23.0 Potential for Runoff: None

Comments:

O&M Index:	0.00	O&M Quick:	0000	O&M Rating:	0.00
Structural Index:	0.00	Structural Quick:	0000	Structural Rating:	0.00
Overall Index:	0.00	Overall Quick:	0000	Overall Rating:	0.00

Wednesday, May 3, 2023

	Position	Code	Observation	Video (sec)	Grade
1-903-04	17				
	.0	MGP	General Photo	10	NA
ш	1.9	MGP	General Photo	28	NA
ш	2.6	IS	Infil Stain	43	NA
ш	3.6	MGO	General Observation	56	NA
Ш					
.					
Ш					
ш					
ш					
ш					
- 11					




General Photo Description: Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Step: NO Remarks:

MGP

Wednesday, May 3, 2023 2

Code:



Code: MGP

Description: General Photo

Distance (ft): 1.9
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:



Code: IS

Description: Infil Stain

Distance (ft): 2.6
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 9

Clock To:

1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:



Code: MGO

Description: General Observation

Distance (ft): 3.6
Structural Grade: 0

O&M Grade: 0

Clock Start/From:
Clock To:

1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: Ins. Comp.

Wednesday, May 3, 2023 3