Manhole Inspection Report



Date: 03/21/2018 Weather: Coding:

 MH#:
 M-903-056
 Owner:
 NA
 Len. Surveyed:
 5.0

 P.O.#:
 Surveyor:
 John Kuglmaier
 Rim to Invert:
 5.9

Customer: Cert. #: U-1215-07002349 Wall Material: Concrete

(reinforced)

RZMACP

Street: 330' South of Hwy 6. 613' East of H Project: Hobart, IN

City: Hobart, IN GPS Northing: 0.0 Location: GPS Easting: 0.0

Drain Area: Northeast GPS Accuracy: Nearest Meter

Cover Shape: Circular Evidence of Surcharge: No
Cover Size: 23.0 Potential for Runoff: None

Comments:

O&M Index:	0.00	O&M Quick:	0000	O&M Rating:	0.00
Structural Index:	0.00	Structural Quick:	0000	Structural Rating:	0.00
Overall Index:	0.00	Overall Quick:	0000	Overall Rating:	0.00

Wednesday, May 3, 2023

Position	Code	Observation	Video (sec)	Grade
J- 903-0 56				
.0	MGP	General Photo	10	NA
2.2	MGP	General Photo	28	NA
3.9	MGO	General Observation	46	NA



Description:	General Photo
Distance (ft): Structural Grade:	.0 0
O&M Grade:	0
Clock Start/From: Clock To:	
1st Value: 2nd Value:	
Value Percent: Step:	NO
Remarks:	

MGP

Wednesday, May 3, 2023 2

Code:



Code: MGP

Description: **General Photo**

Distance (ft): 2.2 Structural Grade: 0 0 O&M Grade:

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:



Code: MGO

Description: **General Observation**

Distance (ft): 3.9 Structural Grade: 0 0 O&M Grade: Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: Ins. Comp.

Wednesday, May 3, 2023