## **Manhole Inspection Report**



Date: 03/20/2018 Weather:

Hobart, IN

Circular

23.0

M-903-067 MH#: Owner: NA P.O.#: John Kuglmaier Surveyor:

Rim to Invert: 4.0 U-1215-07002349 Concrete Cert. #: Wall Material:

Hobart, IN

Coding:

Len. Surveyed: 3.1

(reinforced)

**RZMACP** 

Street: City:

Customer:

122' West of County Line Rd. 495' S Project:

**GPS Northing:** 2912200.281

Location:

GPS Easting: 2912200.281

Drain Area: Northeast GPS Accuracy: **Sub-Meter** 

Cover Shape: Cover Size:

Evidence of Surcharge: No

Potential for Runoff: None

Comments:

O&M Index: Structural Index: Overall Index:

0.00 O&M Quick: 0.00 Structural Quick:

0.00

Overall Quick:

0000 O&M Rating: 0000 Structural Rating: 0000

Overall Rating:

0.00 0.00 0.00

Wednesday, May 3, 2023 1

Position	Code	Observation	Video (sec)	Grade
и-903-967				
.0	MGP	General Photo	10	NA
1.4	MGP	General Photo	27	NA
2.4	MGO	General Observation	43	NA
Camera Direction				



Description:	General Photo
Distance (ft): Structural Grade: O&M Grade:	.0 0 0
Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent:	
Step: Remarks:	NO

MGP

Wednesday, May 3, 2023

Code:





Code: MGP

Description: General Photo


Distance (ft): 1.4
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:



Code: MGO

Description: General Observation

Distance (ft): 2.4
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: Ins. Comp.