## **Manhole Inspection Report**



Date:

Customer:

05/11/2018

Weather:

Cert. #:

**RZMACP** 

MH#:

M-904-005

Owner: NA Len. Surveyed:

Coding:

13.1

P.O.#:

Surveyor: Jen Costello

Rim to Invert:

13.4 Wall Material:

Concrete

Street:

**Intersection of Hickey St. and Union** Project:

(reinforced)

City:

Hobart, IN

**GPS Northing:** 

U-907-5518

Hobart, IN 2912393.958

Location:

2912393.958

Drain Area:

GPS Easting:

Cover Shape:

Northeast

GPS Accuracy: **Sub-Meter** 

Cover Size:

Circular 22.5

Evidence of Surcharge: Potential for Runoff: None

0000

No

Comments:

O&M Index:

0.00 O&M Quick: O&M Rating:

0.00 0.00

Structural Index: Overall Index:

0.00 Structural Quick: 0.00 Overall Quick:

0000 Structural Rating: 0000

0.00 Overall Rating:

Position	Code	Observation	Video (sec)	Grade
M-904-905				
.0	MGO	General Observation	10	NA
1.5	MGO	General Observation	26	NA
13.1	MGO	General Observation	62	NA
Camera Direction				



Distance (ft):

.0

MGO

Structural Grade:

O&M Grade:

Clock Start/From:

Clock To:

1st Value:

2nd Value:


Value Percent:

Step:

NO

Code:

Remarks: ACCESS MH



Code: MGO

Description: General Observation

Distance (ft): 1.5
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: UNDERSIDE OF FRAME



Code: MGO

Description: General Observation

Distance (ft): 13.1
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: END SURVEY

Wednesday, May 3, 2023