Manhole Inspection Report



05/07/2018 Date: Coding: Weather:

MH#: M-904-035 Owner: NA Len. Surveyed: 6.3 P.O.#: Surveyor: Jen Costello Rim to Invert: 5.9

Customer: U-907-5518 Wall Material: Concrete Cert. #:

(reinforced)

RZMACP

W. Cleveland Terrace. 816' North of Project: Hobart, IN Street:

City: Hobart, IN GPS Northing: 2910849.028

GPS Easting: Drain Area: Northeast **GPS Accuracy:** Sub-Meter

Cover Shape: Circular Evidence of Surcharge: No Potential for Runoff: Cover Size: 22.5 None

Comments:

Location:


O&M Index:	0.00	O&M Quick:	0000	O&M Rating:	0.00
Structural Index:	0.00	Structural Quick:	0000	Structural Rating:	0.00
Overall Index:	0.00	Overall Quick:	0000	Overall Rating:	0.00

2910849.028

1 Wednesday, May 3, 2023

	Position	Code	Observation	Video (sec)	Grade
M-904-03	35				
	0	MGP	General Photo	10	NA
- 11	2.0	MGO	General Observation	27	NA
- 11	6.3	MGO	General Observation	49	NA
Camera Direction					

Code:



Description:	General Photo
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	ACCESS MH

MGP

Wednesday, May 3, 2023



Code: MGO

Description: General Observation

Distance (ft): 2.0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: UNDERSIDE OF FRAME



Code: MGO

Description: General Observation

Distance (ft): 6.3
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: END SURVEY