Manhole Inspection Report



Date:

05/15/2018

Weather:

Coding:

RZMACP

8.0

8.6

MH#:

M-904-047

Owner: NA Len. Surveyed:

P.O.#:

Surveyor: Jen Costello Rim to Invert:

Customer:

U-907-5518 Cert. #:

Wall Material:

Concrete (reinforced)

Street: City:

Intersection of Hickey St. and Rush S Project:

Hobart, IN

GPS Northing:

2910268.413

Location:

GPS Easting:

2910268.413

Drain Area: Cover Shape: Northeast

Hobart, IN

GPS Accuracy:

Sub-Meter No

Cover Size:

Circular 22.5

Evidence of Surcharge:

Potential for Runoff: None

Comments:

O&M Index:

0.00

O&M Quick: 3.00 Structural Quick:

0000 3100 3100

O&M Rating:

0.00 3.00 3.00

Structural Index: Overall Index:

3.00 Overall Quick: Structural Rating: Overall Rating:

Wednesday, May 3, 2023

1

Posit	ion Code	Observation	Video (sec)	Grade
M-904-047				
.0	FL	Fracture Longitudinal	10	S 3
2.3	MGO	General Observation	29	NA
8.0	MGO	General Observation	54	NA
Camera Direction				



Code: FL
Description: Fracture Longitudinal

Distance (ft): .0
Structural Grade: 3
O&M Grade: 0
Clock Start/From: 10
Clock To:
1st Value:
2nd Value:
Value Percent:
Step: NO
Remarks:

Wednesday, May 3, 2023 2



Code: MGO

Description: General Observation

Distance (ft): 2.3
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: end survey



Code: MGO

Description: General Observation

Distance (ft): 8.0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: end survey

Wednesday, May 3, 2023 3