## **Manhole Inspection Report**



Date:

05/09/2018

Weather:

NA

Coding:

**RZMACP** 

MH#:

M-905-014

Owner:

Len. Surveyed: 13.4 Rim to Invert: 13.8

P.O.#: Customer: Surveyor: Cert. #:

Jen Costello U-907-5518

Wall Material:

Concrete (reinforced)

Street: City:

State Rd. 130. 529' East of Hobart R Project:

**GPS Northing:** 

Hobart, IN 2910299.401

Location:

Hobart, IN

Drain Area:

GPS Easting:

2910299.401

Cover Shape:

Southeast

GPS Accuracy:

**Sub-Meter** 

Cover Size:

Circular 22.5

Evidence of Surcharge: No

Potential for Runoff: None

Comments:

O&M Index:

2.00 0.00

O&M Quick: Structural Quick:

2100 0000

O&M Rating: Structural Rating:

2.00 0.00 2.00

Structural Index: Overall Index:

2.00 Overall Quick:

2100 Overall Rating:

Wednesday, May 3, 2023 1

| Position         | Code | Observation             | Video (sec) | Grade |
|------------------|------|-------------------------|-------------|-------|
| 1-905-014        |      |                         |             |       |
| .0               | MGP  | General Photo           | 10          | NA    |
| 2.1              | MGO  | General Observation     | 28          | NA    |
| 12.0             | DSGV | Deposits Settled Gravel | 61          | M 2   |
| Camera Direction |      |                         |             |       |




Description: **General Photo** Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: NO Step: Remarks: **ACCESS MH** 

MGP

Wednesday, May 3, 2023 2

Code:



Code: MGO

Description: General Observation

Distance (ft): 2.1
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: UNDERSIDE OF FRAME



Code: **DSGV** 

Description: Deposits Settled Gravel

Distance (ft): 12.0
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 12
Clock To: 12
1st Value:

2nd Value:

Value Percent: 5.000 Step: NO

Remarks:

Wednesday, May 3, 2023 3