Manhole Inspection Report



Date:

05/08/2018

Weather:

Coding: **RZMACP**

MH#:

M-905-028

Owner: NA Len. Surveyed: 2.5

P.O.#:

Surveyor: Jen Costello U-907-5518 Cert. #:

Rim to Invert:

Concrete Wall Material:

(reinforced)

Street:

Customer:

445' West of Shelby St. 567' North of Project:

Hobart, IN

City:

Hobart, IN

GPS Northing: 2910633.731

Location:

GPS Easting:

2910633.731

Drain Area:

Southeast

GPS Accuracy: **Sub-Meter**

Cover Shape: Cover Size:

Circular

22.5

Evidence of Surcharge: No

Potential for Runoff: None

Comments:

O&M Index:

0.00

O&M Quick: Structural Quick:

0000 3100

3100

O&M Rating: Structural Rating:

Overall Rating:

0.00 3.00 3.00

Structural Index: Overall Index:

3.00 3.00 Overall Quick:

Wednesday, May 3, 2023

	Position	Code	Observation	Video (sec)	Grade
M-905-02	8				
	.0	MGP	General Photo	10	NA
- 11	.8	SAV	Surface Aggregate Visible	23	S 3
- 11	2.5	MGO	General Observation	37	NA
Camera Direction					

Code:



Description:	General Photo
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	access mh

MGP

Wednesday, May 3, 2023



Code: SAV

Description: Surface Aggregate Visible

Distance (ft): .8
Structural Grade: 3
O&M Grade: 0
Clock Start/From: 12
Clock To: 12
1st Value:

2nd Value: Value Percent:

Step: NO

Remarks:

2nd Value: Value Percent:



Code: MGO

Description: General Observation

Distance (ft): 2.5
Structural Grade: 0
O&M Grade: 0
Clock Start/From:
Clock To:
1st Value:

Step: NO

Remarks: end survey

Wednesday, May 3, 2023 3