

Date:	04/22/2018	Weather:		Coding:	RZMACP
MH#:	M-906-004	Owner:	NA	Len. Surveyed:	11.9
P.O.#:		Surveyor:	John Kuglmaier	Rim to Invert:	11.6
Customer:	8.7	Cert. #:	U-1215-07002349	Wall Material:	Concrete (reinforced)
Street:	Intersection of 9th PI. and Sullivan D Project: Hobart, IN				
City:	Hobart, IN	0	GPS Northing:	0.0	
Location:		0	GPS Easting:	0.0	
Drain Area:	Southeast	GPS Accuracy: Evidence of Surcharge:		Nearest Meter Yes	
Cover Shape:	Circular				
Cover Size: Comments:	22.5	F	Potential for Runoff:	None	
O&M Index:	2.00	O&M Quick:	2100	O&M Rating:	2.00
Structural Index:	0.00	Structural Quic	k: 0000	Structural Rating:	0.00
Overall Index:	2.00	Overall Quick:	2100	Overall Rating:	2.00

	Position	Code	Observation	Video (sec)	Grade
1-906-00	04				
Y.	.0	MGP	General Photo	10	NA
	3.1	MGP	General Photo	30	NA
	8.2	DAZ	Deposits Attached Other	54	M 2
	11.1	MGO	General Observation	71	NA
,					



Code: Description:	MGP General Photo
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	



Code:	MGP
Description:	General Photo
Distance (ft):	3.1
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	



Code:	DAZ
Description:	Deposits Attached Other

Distance (ft):	8.2
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	12
Clock To:	12
1st Value:	
2nd Value:	
Value Percent:	5.000
Step:	NO
Remarks:	Mixed materials



Code: Description:	MGO General Observation
Distance (ft):	11.1
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	Ins. Comp.