Manhole Inspection Report



Date: 04/22/2018 Weather: Coding: RZMACP

 MH#:
 M-906-011
 Owner:
 NA
 Len. Surveyed:
 5.5

 P.O.#:
 Surveyor:
 John Kuglmaier
 Rim to Invert:
 5.6

Customer: 8.7 Cert. #: U-1215-07002349 Wall Material: Concrete

(reinforced)

Street: 10th St. 553' West of Duck Cr. Ct. Project: Hobart, IN

City: Hobart, IN GPS Northing: 0.0 Location: GPS Easting: 0.0

Drain Area: Southeast GPS Accuracy: Nearest Meter

Cover Shape: Circular Evidence of Surcharge: No
Cover Size: Potential for Runoff: None

Comments:

O&M Index:	2.00	O&M Quick:	2100	O&M Rating:	2.00
Structural Index:	0.00	Structural Quick:	0000	Structural Rating:	0.00
Overall Index:	2.00	Overall Quick:	2100	Overall Rating:	2.00

Wednesday, May 3, 2023

Position	Code	Observation	Video (sec)	Grade
1-906-011				
.0	MGP	General Photo	10	NA
2.2	DSF	Deposits Settled Fine	26	M 2
2.6	MGP	General Photo	41	NA
4.6	MGO	General Observation	58	NA
Camera Direction				



General Photo	
.0	
0	
0	
NO	

MGP

Wednesday, May 3, 2023

Code:



Code: DSF

Description: Deposits Settled Fine

Distance (ft): 2.2
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 12
Clock To: 12
1st Value:

2nd Value:

Value Percent: 5.000 Step: NO

Remarks:



Code: MGP

Description: General Photo

Distance (ft): 2.6
Structural Grade: 0
O&M Grade: 0
Clock Start/From:
Clock To:
1st Value:

2nd Value: Value Percent:

Step: NO

Remarks:



Code: MGO

Description: General Observation

Distance (ft): 4.6
Structural Grade: 0

O&M Grade: 0

Clock Start/From:
Clock To:

1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: Ins. Comp.

Wednesday, May 3, 2023 3