## **Manhole Inspection Report**



Date: 04/21/2018 Weather: Coding: RZMACP

 MH#:
 M-907-017
 Owner:
 NA
 Len. Surveyed:
 9.5

 P.O.#:
 Surveyor:
 Jen Costello
 Rim to Invert:
 9.9

Customer: Cert. #: U-907-5518 Wall Material: Concrete

(reinforced)

Street: 10th St. and Union St. Project: Hobart, IN

City: Hobart, IN GPS Northing: 0.0 Location: GPS Easting: 0.0

Drain Area: Southeast GPS Accuracy: Nearest Meter


Cover Shape: Circular Evidence of Surcharge: No
Cover Size: Potential for Runoff: None

Comments:

O&M Index:	2.00	O&M Quick:	2200	O&M Rating:	4.00
Structural Index:	0.00	Structural Quick:	0000	Structural Rating:	0.00
Overall Index:	2.00	Overall Quick:	2200	Overall Rating:	4.00

Wednesday, May 3, 2023

Po	osition	Code	Observation	Video (sec)	Grade				
M-907-017	M-907-017								
.0		MGO	General Observation	10	NA				
1.3	2	IW	Infil Weeper	24	M 2				
2.:	1	MGP	General Photo	40	NA				
/6.:	1	IW	Infil Weeper	61	M 2				
9.!	5	MGO	General Observation	79	NA				
Camera Direction									



Code: MGO
Description: General Observation

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent:

Step: NO

Remarks: ACCESS MH



Code: IW

Description: Infil Weeper

Distance (ft): 1.2
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 12
Clock To: 12

1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:



Code: MGP

Description: General Photo

Distance (ft): 2.1
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: UNDERSIDE OF FRAME



Code: IW

Description: Infil Weeper

Distance (ft): 6.1
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 12
Clock To: 12
1st Value:
2nd Value:

Value Percent:

Step: NO

Remarks:

Wednesday, May 3, 2023 3



Code: MGO

Description: General Observation

Distance (ft): 9.5
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: END SURVEY