Profile/Photo Observation Report

0.00

Overall Quick:

Overall Index:



0.00


Date:	05/07/2018	Weather:		Coding:	PACP 6.0	
Pipe Length (ft		Owner:	City of Hobart	Pre Clean:	No Pre-Cleaning	
P.O.#:	614	Surveyor:	M. Pielacha	PSR:		
Customer:	City of Hobart	Clean Date:		Shape:	С	
Street:	Off State Road 130		Flow Control:	Not Controlled	Not Controlled	
City:	Hobart, IN		Year Renewed:			
Location:	Easement/Right of Way		Tape/Media #:	DEP 614		
Purpose:	Routine Assessment		Dia/Height:	6"		
Use:	Sanitary		Material:	PVC		
Drain Area:			Lining:			
Category:	NA					
Comment:	5-21-2018					
Location Details:		Direction of Survey:	Downstream			
US MH:	M-1006-008	DS MH:	M-1006-008T	Total Length Surveyed (ft): 35.7	
0&M Index:	0.00	O&M Quick:	0000	O&M Rating:	0.00	
tructural Index:	0.00	Structural Qui	ick: 0000	Structural Rating:	0.00	

0000

Overall Rating:


	Position	Code	Observation	Video (sec)	Grade
M-1006	008				
	.0	AMH	Manhole	0	NA
- 11	\0	MWL	Water Level	9	NA
- 11	28.9	MWL	Water Level	68	NA
- 11	32.6	MSA	Abandoned Survey	118	NA
Camera Direction					
N-1006-0	08Т				

Code:



Description:	Manhole	
5: (6)		
Distance (ft):	.0	
Structural Grade:	0	
O&M Grade:	0	
Clock Start/From:		
Clock To:		
1st Value:		
2nd Value:		
Value Percent:		
Continuous Index:		
Within 8" of Joint:	NO	
Remarks:	M-1006-008	

AMH



Code: MWL
Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:
Clock To:
1st Value:

2nd Value: Value Percent:

t: **5.000**

Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: MWL
Description: Water Level

Distance (ft): 28.9
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 50.000

Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: MSA

Description: Abandoned Survey

Distance (ft): 32.6
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: underwater sediment