

Profile/Photo Observation Report



Date:	04/10/2018	Weather:		Coding:	PACP 6.0
Pipe Length (ft):		Owner:	City of Hobart	Pre Clean:	Not Known
P.O.#:	227	Surveyor:	B. Helbling	PSR:	
Customer:	City of Hobart	Clean Date:		Shape:	C

Street:	South Liverpool Road	Flow Control:	Not Controlled		
City:	Hobart, IN	Year Renewed:			
Location:	Light Highway	Tape/Media #:	DEP227		
Purpose:	Routine Assessment	Dia/Height:	15"		
Use:	Sanitary	Material:	VCP		
Drain Area:		Lining:			
Category:	NA				
Comment:	YES501824 Submittal 2				
Location Details:		Direction of Survey:	Upstream		
US MH:	M-208-023A	DS MH:	M-208-023	Total Length Surveyed (ft):	23.0

O&M Index:	1.80	O&M Quick:	3122	O&M Rating:	9.00
Structural Index:	0.00	Structural Quick:	0000	Structural Rating:	0.00
Overall Index:	1.80	Overall Quick:	3122	Overall Rating:	9.00

Position	Code	Observation	Video (sec)	Grade
M-208-023				
.0	AMH	Manhole	0	NA
.0	MWL	Water Level	12	NA
3.1	DSF	Deposits Settled Fine	67	M 2
3.1	DAR	Deposits Attached Ragging	176	M 3
8.6	RFJ	Roots Fine Joint	279	M 1
13.8	RFJ	Roots Fine Joint	369	M 1
23.0	AMH	Manhole	662	NA
23.0	DSF	Deposits Settled Fine	735	M 2



Code: **AMH**
Description: **Manhole**

Distance (ft): **.0**
Structural Grade: **0**
O&M Grade: **0**
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:
Within 8" of Joint: **NO**
Remarks: **M-208-023**



Code: **MWL**
Description: **Water Level**

Distance (ft): **.0**
Structural Grade: **0**
O&M Grade: **0**
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent: **10.000**
Continuous Index:
Within 8" of Joint: **NO**
Remarks:



Code: **DSF**
Description: **Deposits Settled Fine**

Distance (ft): **3.1**
Structural Grade: **0**
O&M Grade: **2**
Clock Start/From: **5**
Clock To: **7**
1st Value:
2nd Value:
Value Percent: **5.000**
Continuous Index:
Within 8" of Joint: **NO**
Remarks:



Code: **DAR**
Description: **Deposits Attached Ragging**

Distance (ft): **3.1**
Structural Grade: **0**
O&M Grade: **3**
Clock Start/From: **8**
Clock To: **4**
1st Value:
2nd Value:
Value Percent: **15.000**
Continuous Index:
Within 8" of Joint: **YES**
Remarks:



Code: **RFJ**
Description: **Roots Fine Joint**

Distance (ft): **8.6**
Structural Grade: **0**
O&M Grade: **1**
Clock Start/From: **8**
Clock To: **4**
1st Value:
2nd Value:
Value Percent:
Continuous Index:
Within 8" of Joint: **YES**
Remarks:



Code: **RFJ**
Description: **Roots Fine Joint**

Distance (ft): **13.8**
Structural Grade: **0**
O&M Grade: **1**
Clock Start/From: **8**
Clock To: **10**
1st Value:
2nd Value:
Value Percent:
Continuous Index:
Within 8" of Joint: **YES**
Remarks:



Code: **AMH**
Description: **Manhole**

Distance (ft): **23.0**
Structural Grade: **0**
O&M Grade: **0**
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:
Within 8" of Joint: **NO**
Remarks: **M-208-023A. New MH found**



Code:	DSF
Description:	Deposits Settled Fine
Distance (ft):	23.0
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	5
Clock To:	7
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	