## **Profile/Photo Observation Report**



Date: 04/14/2018 Weather: Coding: PACP 6.0

Pipe Length (ft): 368.3 Owner: NA Pre Clean: Not Known

P.O.#: Surveyor: **Jen Costello** PSR: **P-1004-007-008** 

Customer: Clean Date: 01/01/1900 Shape: C

Street: CORAL DR Flow Control: Not Controlled

City: Hobart, IN Year Renewed:
Location: Other Tape/Media #:

Purpose: Not Known Dia/Height: 10"
Use: Sanitary Material: PVC

Drain Area: NA Lining:

Comment: NULL - CNA DC at MH-M-804-023

NA

Category:

Location Details: Direction of Survey: **Downstream** 

US MH: M-1004-008 DS MH: M-1004-007 Total Length Surveyed (ft): 362.0

2.00 2600 12.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 2.00 2600 12.00 Overall Index: Overall Quick: Overall Rating:

AMH MWL DAGS(S01)	Manhole Water Level	10	NA
MWL		10	NΑ
	Water Level		IVA
DAGS(S01)		21	NA
()	Deposits Attached Grease	33	M 2
DAGS(F01)	Deposits Attached Grease	85	M 2
DAGS	Deposits Attached Grease	122	M 2
TF	Tap Factory	137	NA
MWL	Water Level	186	NA
MWL	Water Level	252	NA
TF	Tap Factory	317	NA
TF	Tap Factory	456	NA
TF	Tap Factory	482	NA
MWL	Water Level	620	NA
TF	Tap Factory	644	NA
DAGS	Deposits Attached Grease	658	M 2
TFA	Tap Factory Active	694	NA
TF	Tap Factory	828	NA
AMH	Manhole	927	NA
	TF MWL TF TF TF MWL TF DAGS TFA TF	TF Tap Factory  MWL Water Level  MWL Water Level  TF Tap Factory  TF Tap Factory  MWL Water Level  TF Tap Factory  MWL Water Level  TF Tap Factory  DAGS Deposits Attached Grease  TFA Tap Factory  Tap Factory	TF         Tap Factory         137           MWL         Water Level         186           MWL         Water Level         252           TF         Tap Factory         317           TF         Tap Factory         456           TF         Tap Factory         482           MWL         Water Level         620           TF         Tap Factory         644           DAGS         Deposits Attached Grease         658           TFA         Tap Factory Active         694           TF         Tap Factory         828

Code:



Description:	Manhole	
Distance (ft):	.0	
Structural Grade:	0	
O&M Grade:	0	
Clock Start/From:		
Clock To:		
1st Value:		
2nd Value:		
Value Percent:		
Continuous Index:		
Within 8" of Joint:	NO	
Remarks:	M-1004-008	

 $\mathsf{AMH}$ 



Code: MWL

Description: **Water Level** 

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From:

Clock To:

1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint:

Remarks:

5.000


NO

Code: DAGS

Description: **Deposits Attached Grease** 

Distance (ft): .0 Structural Grade: 0 O&M Grade: 2 Clock Start/From: 8 Clock To: 7 1st Value: 2nd Value:

Value Percent: 5.000 Continuous Index: **S01** Within 8" of Joint: NO



Code: DAGS

Description: Deposits Attached Grease

Distance (ft): 20.4
Structural Grade: 0

O&M Grade: 2

Clock Start/From: 8

Clock To: 7

1st Value:

2nd Value:

Value Percent: 5.000
Continuous Index: F01
Within 8" of Joint: NO

Remarks:

Code: DAGS

Description: Deposits Attached Grease




Distance (ft): 33.2
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 7
Clock To: 11

1st Value: 2nd Value:

Value Percent: 10.000

Continuous Index:

Within 8" of Joint: NO



Code: **TF** 

Description: Tap Factory

Distance (ft): 34.1
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 10

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: MWL

Description: Water Level

Distance (ft): 52.3
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: **30.000** 

Continuous Index:

Within 8" of Joint: NO



Code: MWL
Description: Water Level

Distance (ft): 79.1
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: **TF** 


Description: Tap Factory

Distance (ft): 106.0
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 11

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: **TF** 

Description: Tap Factory

Distance (ft): 169.2
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 1

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **TF** 


Description: Tap Factory

Distance (ft): 176.0
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 11

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: MWL
Description: Water Level

Distance (ft): 239.1
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 20.000

Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: **TF** 

Description: Tap Factory

Distance (ft): 245.0
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 1

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: DAGS

Description: Deposits Attached Grease

Distance (ft): 246.1
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 8
Clock To: 9

1st Value: 2nd Value:


Value Percent: 5.000

Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: TFA


Description: Tap Factory Active

Distance (ft): 258.0
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 1

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: **TF** 

Description: Tap Factory

Distance (ft): 318.7
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 11

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: AMH
Description: Manhole

Distance (ft): 362.0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: M-1004-007