Profile/Photo Observation Report



Profile/Photo Observation Report										
Date:	10/21/2021	Weather:			Coding:	PACP 6.0				
Pipe Length (ft):		Owner:	Hobart, IN		Pre Clean:	Not Known				
P.O.#:	P.O.#: 924_1		M. Pielacha		PSR:	M-705-021_M-706-040				
Customer:	Hobart, IN	Clean Date:			Shape:	С				
Street:	Water Street		Flow Control:							
City:	Hobart, IN		Year Renewed:	;						
Location:	Light Highway		Tape/Media #:		924					
Purpose:	Routine Assessment		Dia/Height:		10"					
Use:	Sanitary		Material:		PVC					
Drain Area:			Lining:							
Category:	NA									
Comment:										
Location Detai	ls:		Direction of Su	rvey:	Upstream					
US MH:	M-705-021	DS MH:	M-706-040		Total Length Surveyed (ft)	: 280.9				
O&M Index:	0.00	O&M Quick:	00	000	O&M Rating:	0.00				
Structural Index:	0.00	Structural Qu	ick: 00	000	Structural Rating:	0.00				
Overall Index:	0.00	Overall Quick		000	Overall Rating:	0.00				

Thursday, May 4, 2023

	Position	Code	Observation	Video (sec)	Grade
706-0	40				
	0	AMH	Manhole	0	NA
Camera Direction	\\ <u>.</u> 0	MWL	Water Level	23	NA
	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	TF	Tap Factory	40	NA
	9.6	TF	Tap Factory	63	NA
	52.9	TFA	Tap Factory Active	118	NA
	66.4	TF	Tap Factory	144	NA
	116.7	TF	Tap Factory	204	NA
	139.6	TF	Tap Factory	246	NA
	// <u>162.0</u>	TF	Tap Factory	282	NA
	205.9	TF	Tap Factory	357	NA
	280.9	AMH	Manhole	752	NA
705,0					

Code:



Description: Manhole Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint: NO Remarks: M-706-040

AMH



MWL Code: Description: **Water Level**

Distance (ft): .0 Structural Grade: 0 0 O&M Grade:

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 10.000

Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: TF Description: **Tap Factory**

Distance (ft): 2.9 Structural Grade: 0 O&M Grade: Clock Start/From: 10 Clock To:

1st Value: 4.000

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks:

3 Thursday, May 4, 2023



Description: Tap Factory

Distance (ft): 9.6
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 2

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: TFA

Description: Tap Factory Active

Distance (ft): 52.9
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 3

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks:



Description: Tap Factory

Distance (ft): 66.4
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 10

Clock To:


1st Value: **4.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: **TF**

Description: Tap Factory

Distance (ft): 116.7
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 9

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks:



Description: Tap Factory

Distance (ft): 139.6
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 3

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: **TF**

Description: Tap Factory

Distance (ft): 162.0
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 10

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks:



Description: Tap Factory

Distance (ft): 205.9
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 9

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: AMH
Description: Manhole

Distance (ft): 280.9
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: NO

Remarks: M-705-021