Profile/Photo Observation Report



Date: 04/15/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 128.2 Owner: NA Pre Clean: **Not Known** P.O.#: PSR: P-1004-019-018

Selasie Honu

Customer: Clean Date: 01/01/1900 Shape:

Drexel Dr. Flow Control: **Not Controlled** Street:

Surveyor:

City: Hobart, IN Year Renewed: Other Tape/Media #: Location:

Purpose: **Not Known** Dia/Height: 8" **PVC** Use: Sanitary Material:

NA Drain Area: Lining:

NA Category:

Comment: **Location Details:** Direction of Survey: **Downstream**


US MH: M-1004-019 Total Length Surveyed (ft): M-1004-018 DS MH: 139.6

0.00 0000 0.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 0.00 0000 0.00 Overall Rating: Overall Index: Overall Quick:

Position	Code	Observation	Video (sec)	Grade
1004-018				
0.	AMH	Manhole	10	NA
0.	MWL	Water Level	21	NA
0.\\\	TF	Tap Factory	32	NA
\\4.4	MGO	General Observation	55	NA
21.5	TFA	Tap Factory Active	105	NA
46.1	TF	Tap Factory	169	NA
/71.2	TF	Tap Factory	235	NA
89.5	TF	Tap Factory	288	NA
136.1	TFA	Tap Factory Active	396	NA
11120.6	AMH	Manhole	417	NA
139.6	Alvin	Walliote	417	NA .
139.6	AIVIN	IVIAIIIOLE	41/	IVA

Code:


Description:



·	
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-1004-018

AMH

Manhole



Code: MWL Description: **Water Level**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint:

Remarks:

5.000

NO

Code: TF Description: **Tap Factory**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: 10

Clock To:

1st Value: 4.000

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: MGO

Description: General Observation

Distance (ft): 4.4
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks: switching to rear view of camera

NO



Code: TFA


Description: Tap Factory Active

Distance (ft): 21.5
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: **TF**

Description: Tap Factory

Distance (ft): 46.1
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 11

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **TF**

Description: Tap Factory

Distance (ft): 71.2
Structural Grade: 0


O&M Grade: 0

Clock Start/From: 2

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: **TF**

Description: Tap Factory


Distance (ft): 89.5
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 11

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: TFA


Description: Tap Factory Active

Distance (ft): 136.1
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 10

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: AMH
Description: Manhole

Distance (ft): 139.6
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: M-1004-019