Profile/Photo Observation Report



Date: 04/14/2018 Weather: Coding: PACP 6.0

Pipe Length (ft): 254.4 Owner: NA Pre Clean: Not Known

P.O.#: Surveyor: **Jen Costello** PSR: **P-1004-032-031**

Customer: Clean Date: 01/01/1900 Shape: C

Street: E CLEVELAND AVE Flow Control: Not Controlled

City: Hobart, IN Year Renewed:
Location: Other Tape/Media #:

Purpose: Not Known Dia/Height: 8"
Use: Sanitary Material: PVC

Drain Area: **NA** Lining:

Category: NA

Comment:


Location Details: Direction of Survey: Downstream

US MH: M-1004-031 DS MH: M-1004-032 Total Length Surveyed (ft): 248.8

2.00 2100 2.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 2.00 2100 2.00 Overall Rating: Overall Index: Overall Quick:

	Position	Code	Observation	Video (sec)	Grade
1004	031				
\bigvee	0. //	AMH	Manhole	10	NA
	0.	MWL	Water Level	21	NA
	79.3	DAGS	Deposits Attached Grease	191	M 2
	79.8	TF	Tap Factory	204	NA
	111.1	MWL	Water Level	278	NA
	114.7	TF	Tap Factory	297	NA
ш	166.9	TF	Tap Factory	413	NA
	190.2	TF	Tap Factory	472	NA
ш	211.4	MWL	Water Level	526	NA
	245.1	TF	Tap Factory	606	NA
	248.8	AMH	Manhole	627	NA
ш					

Code:



Description:	Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-1004-031

AMH



Code: MWL

Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint:


Remarks:

5.000

NO

Code: DAGS

Description: Deposits Attached Grease



Distance (ft): 79.3
Structural Grade: 0
O&M Grade: 2


Clock Start/From: 8
Clock To: 4

1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: NO



Description: Tap Factory

Distance (ft): 79.8
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 10

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: MWL

Description: Water Level

Distance (ft): 111.1
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 40.000

Continuous Index:

Within 8" of Joint: NO



Description: Tap Factory


Distance (ft): 114.7
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **TF**


Description: Tap Factory

Distance (ft): 166.9
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 10

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Description: Tap Factory

Distance (ft): 190.2
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: MWL

Description: Water Level

Distance (ft): 211.4
Structural Grade: 0

O&M Grade: 0


Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 40.000

Continuous Index:

Within 8" of Joint: NO



Description: Tap Factory

Distance (ft): 245.1
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 10

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: AMH
Description: Manhole

Distance (ft): 248.8
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: NO

Remarks: M-1004-032