## **Profile/Photo Observation Report**

Customer:

Location:



Date: 04/11/2018 Weather: Coding: PACP 6.0

Pipe Length (ft): 95.3 Owner: NA Pre Clean: Not Known

P.O.#: Surveyor: **Jen Costello** PSR: **P-1004-073-072** 

01/01/1900

Tape/Media #:

Shape:

Street: TULIP LN Flow Control: Not Controlled

Clean Date:

City: Hobart, IN Year Renewed:

Purpose: Not Known Dia/Height: 8"
Use: Sanitary Material: PVC

Drain Area: NA Lining:

Category: NA

Other

Comment:

Location Details: Direction of Survey: Downstream

US MH: M-1004-072 DS MH: M-1004-073 Total Length Surveyed (ft): 93.9

0000 0.00 0.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 0.00 0000 0.00 Overall Rating: Overall Index: Overall Quick:

Position	Code	Observation	Video (sec)	Grade
1004-072				
.0	AMH	Manhole	10	NA
0.	MWL	Water Level	21	NA
21.4	TFA	Tap Factory Active	75	NA
/93.9	AMH	Manhole	232	NA
ш				
1004-073				

Code:



Description:	Manhole		
Distance (ft):	.0		
Structural Grade:	0		
O&M Grade:	0		
Clock Start/From:			
Clock To:			
1st Value:			
2nd Value:			
Value Percent:			
Continuous Index:			
Within 8" of Joint:	NO		
Remarks:	M-1004-072		

AMH



Code: MWL

Description: **Water Level** 

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint:

Remarks:

NO

Code: **TFA** 

**Tap Factory Active** Description:




Distance (ft): 21.4 Structural Grade: 0 O&M Grade: 0 Clock Start/From: 9

Clock To:

Remarks:

1st Value: 4.000

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: AMH
Description: Manhole

Distance (ft): 93.9
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: M-1004-073