


Profile/Photo Observation Report



Date:	04/23/2018	Weather:		Coding:	PACP 4.2
Pipe Length (ft):	343.0	Owner:	City of Hobart	Pre Clean:	No Pre-Cleaning
P.O.#:	2004	Surveyor:	SAN	PSR:	P-904-041-041A
Customer:	Red Zone	Clean Date:		Shape:	C

Street:	149 Bush St	Flow Control:	Not Controlled
City:	Hobart In	Year Renewed:	
Location:	Yard	Tape/Media #:	Deliverable 1
Purpose:	Routine Assessment	Dia/Height:	18"
Use:	Sanitary	Material:	VCP
Drain Area:	Northeast	Lining:	
Category:	NA		
Comment:	426-1/DSMH was not shown on mapping and is covered. Configuration differs from provided mapping.		
Location Details:	Grass between homes	Direction of Survey:	Upstream
US MH:	M-904-041	DS MH:	M-904-041A
		Total Length Surveyed (ft):	343.0

O&M Index:	3.00	O&M Quick:	3300	O&M Rating:	9.00
Structural Index:	0.00	Structural Quick:	0000	Structural Rating:	0.00
Overall Index:	3.00	Overall Quick:	3300	Overall Rating:	9.00

	Position	Code	Observation	Video (sec)	Grade
	.0	AMH	Manhole	40	NA
	.0	MWL	Water Level	67	NA
	.0	MGO	General Observation	94	NA
	124.2	TB	Tap Break-in	267	NA
	129.1	TBD	Tap Break-in Defective	341	M 3
	129.1	DAE	Deposits Attached Encrustation	389	M 3
	324.3	OBZ	Obstacle Other	628	M 3
	343.0	MGO	General Observation	969	NA
	343.0	AMH	Manhole	984	NA



Code: **AMH**
Description: **Manhole**

Distance (ft): **.0**
Structural Grade: **0**
O&M Grade: **0**
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:
Within 8" of Joint: **NO**
Remarks: **M-904-041A**



Code:	MWL
Description:	Water Level
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	10.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code:	MGO
Description:	General Observation
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	infil in manhole



Code:	TB
Description:	Tap Break-in
Distance (ft):	124.2
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	11
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code:	TBD
Description:	Tap Break-in Defective
Distance (ft):	129.1
Structural Grade:	0
O&M Grade:	3
Clock Start/From:	11
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	infil in tap



Code:	DAE
Description:	Deposits Attached Encrustation
Distance (ft):	129.1
Structural Grade:	0
O&M Grade:	3
Clock Start/From:	7
Clock To:	5
1st Value:	
2nd Value:	
Value Percent:	15.000
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	



Code:	OBZ
Description:	Obstacle Other
Distance (ft):	324.3
Structural Grade:	0
O&M Grade:	3
Clock Start/From:	5
Clock To:	7
1st Value:	
2nd Value:	
Value Percent:	15.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	under flow



Code:	MGO
Description:	General Observation
Distance (ft):	343.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	zoomed lasdt 10 ft due to debris

Code:	AMH
Description:	Manhole
Distance (ft):	343.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-904-041