Profile/Ph	oto Observatio	n Report			RedZone
Date:	04/12/2018	Weather:		Coding:	PACP 6.0
Pipe Length (ft	): <b>231.2</b>	Owner:	NA	Pre Clean:	Not Known
P.O.#:		Surveyor:	Jen Costello	PSR:	P-1006-004-003
Customer:		Clean Date:	01/01/1900	Shape:	С
Street:	VERMILLION ST		Flow Control:	Not Controlled	
City:	Hobart, IN		Year Renewed:		
Location:	Yard		Tape/Media #:		
Purpose:	Maintenance Rel	ated	Dia/Height:	8"	
Use:	Sanitary		Material:	PVC	
Drain Area:	NA		Lining:	Cured in Place	
Category:	NA				
Comment:	mh confirmed, flo	ow incorrect.			
Location Detail	s:		Direction of Survey	:: Upstream	
US MH:	M-1006-003	DS MH:	M-1006-004	Total Length Surveyed (ft)	: <b>225.6</b>
0&M Index:	2.00	O&M Quick:	2100	O&M Rating:	2.00
tructural Index:	0.00	Structural Qu	uick: 0000	Structural Rating:	0.00
Overall Index:	2.00	Overall Quick	c: <b>2100</b>	Overall Rating:	2.00

	Position	Code	Observation	Video (sec)	Grad
1-1006-0	004				
$\leq$	.0	AMH	Manhole	10	NA
	\ <u>.</u> 0	MWL	Water Level	21	NA
	67.5	MGO	General Observation	170	NA
	69.1	TFA	Tap Factory Active	185	NA
	77.7	TF	Tap Factory	214	NA
	166.5	DAGS	Deposits Attached Grease	403	M 2
	167.2	TF	Tap Factory	416	NA
=======================================	225.6	AMH	Manhole	547	NA




Code: Description:	AMH Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-1006-004




Code: MWL Description: Water Level

Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code: Description:	MGO General Observation
Distance (ft):	67.5
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	rear camera



Code:	TFA
Description:	Tap Factory Active

Distance (ft):	69.1
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	10
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Distance (ft):77.7Structural Grade:0O&M Grade:0Clock Start/From:1Clock To:11st Value:4.0002nd Value:Yalue Percent:Continuous Index:Yithin 8" of Joint:	Code: Description:	TF Tap Factory
Remarks:	Structural Grade: O&M Grade: Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint:	0 0 1



Code:DAGSDescription:Deposits Attached Grease

Distance (ft):	166.5
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	8
Clock To:	10
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code: Description:	TF Tap Factory
Distance (ft):	167.2
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	1
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code: AMH Description: Manhole

Distance (ft):	225.6
Structural Grade: (	ט
O&M Grade: 0	ט
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-1006-003