Profile/Photo Observation Report

0.00

Overall Quick:

Overall Index:



0.00

Date: Pipe Length (ft)		Weather:		Coding:	DAGD C O
P.O.#:	264	Owner: Surveyor:	City of Hobart B. Helbling	Pre Clean: PSR:	PACP 6.0 Not Known P-1006-011-012
Customer:	City of Hobart	Clean Date:		Shape:	С
Street:	East State Rt 130		Flow Control:	Not Controlled	
City:	Hobart, IN		Year Renewed:		
Location:	Yard		Tape/Media #:	DEP264	
Purpose:	Routine Assessment		Dia/Height:	15"	
Use:	Sanitary		Material:	PVC	
Drain Area:			Lining:		
Category:	NA				
Comment:	5-21-2018				
Location Detail	s:		Direction of Survey:	Upstream	
US MH:	M-1006-012	DS MH:	M-1006-011	Total Length Surveyed (ft)	: 55.5
O&M Index:	0.00	O&M Quick:	0000	O&M Rating:	0.00
Structural Index:	0.00	 _Structural Qu	uick: 0000	Structural Rating:	0.00

0000

Overall Rating:

Thursday, May 4, 2023

M-1006-011 .0 AMH Manhole 0 .0 MWL Water Level 9 55.5 AMH Manhole 168	
.0 AMH Manhole 0 .0 MWL Water Level 9 55.5 AMH Manhole 168	
55.5 AMH Manhole 168	NA
	NA
Camera Direction	NA
M-1006-012	

Code:



Description:	Manhole
Distance (ft)	
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-1006-012

 AMH

Thursday, May 4, 2023 2



Code: MWL

Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: AMH
Description: Manhole

Distance (ft): 55.5
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: M-1006-011

Thursday, May 4, 2023 3