Profile/Photo Observation Report

2.00

Overall Quick:

Overall Index:




18.00

| Profile/Photo Observation Report | | | | | | | | | |
|----------------------------------|------------------------------------|---|------------------------------|-------------------------------|---|--|--|--|--|
| Date: Pipe Length (ft | 01/18/2022): 52.3 YES502259 | Weather: Owner: Surveyor: | City of Hobart S. Bucklin | Coding: Pre Clean: PSR: | PACP 7.0 Heavy Cleaning P-506-026-011 | | | | |
| Customer: | City of Hobart | Clean Date: | 01/17/2021 | Shape: | С | | | | |
| Street: | South Colorado Street | | Flow Control: | Not Controlled | | | | | |
| City: | Hobart, IN | | Year Renewed: | | | | | | |
| Location: | Local rural street | Local rural streets with light traffic, t Tape/Media #: | | | | | | | |
| Purpose: | Routine Assessm | ent | Dia/Height: | 10" | | | | | |
| Use: | Sanitary Sewage | Pipe | Material: | VCP | | | | | |
| Drain Area: | | | Lining: | None | | | | | |
| Category: Comment: | NA | | | | | | | | |
| Location Detail | s: | | Direction of Surve | y: Downstream | | | | | |
| US MH: | M-506-011 | DS MH: | M-506-026 | Total Length Surveyed (ft) | : 52.3 | | | | |
| O&M Index: | 2.00 | O&M Quick: | 2900 | O&M Rating: | 18.00 | | | | |
| Structural Index: | 0.00 | Structural Qu | uick: 0000 | Structural Rating: | 0.00 | | | | |

2900

Overall Rating:

| | Code | Observation | Video (sec) | Grade |
|------|----------|---------------------------|-------------|-------|
| 011 | | | | |
| .0 | AMH | Manhole | 1 | NA |
| .0 | MWL | Miscellaneous Water Level | 89 | NA |
| 4.8 | DSF(S01) | Deposits Settled Fine | 127 | M 2 |
| 30.5 | MWL | Miscellaneous Water Level | 249 | NA |
| 51.2 | DSF(F01) | Deposits Settled Fine | 343 | M 2 |
| 52.3 | AMH | Manhole | 429 | NA |
| | | | | |



| Code: | AMH |
|---------------------|-----------|
| Description: | Manhole |
| | |
| Distance (ft): | .0 |
| Structural Grade: | 0 |
| O&M Grade: | 0 |
| Clock Start/From: | |
| Clock To: | |
| 1st Value: | |
| 2nd Value: | |
| Value Percent: | |
| Continuous Index: | |
| Within 8" of Joint: | NO |
| Remarks: | M-506-011 |
| | |



Code: MWL

Description: **Miscellaneous Water Level**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint: NO

Remarks:

5.000



Code: **DSF**

Description: **Deposits Settled Fine**


Distance (ft): 4.8 Structural Grade: 0 O&M Grade: 2 Clock Start/From: 5 Clock To: 7 1st Value:

2nd Value:

Value Percent: 5.000 Continuous Index: **S01** Within 8" of Joint: YES

Remarks:

3 Tuesday, April 25, 2023



Code: MWL

Description: Miscellaneous Water Level

Distance (ft): 30.5
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:


Value Percent: 15.000

Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: **DSF**

Description: Deposits Settled Fine

Distance (ft): 51.2
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 5
Clock To: 7
1st Value:

2nd Value:

Value Percent: 5.000
Continuous Index: F01
Within 8" of Joint: YES

Remarks:

:



Code: AMH
Description: Manhole

Distance (ft): 52.3
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: M-506-026